# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R  GST Reg. No. 19-9607198-R

## PRE-REPAIR INSPECTION REPORT

| HSBC LIFE (SINGAPORE) PTE LTD | | Ref: | CS3/HSB23003456/Rnp3e2 |
|---|---|---|---|
| 10 MARINA BOULEVARD<br>#48-01 MARINA BAY FINANCIAL CENTRE TOWER<br>2SINGAPORE 018983 | | Date: | 11/04/2023 |
| ATTN: HO WINNIE | | Code: | HSB |

| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | |
|---|---|---|---|---|
| | **Insured Veh.** | SHA 4914L | **Veh. Inspected** | FBJ 9941Z |
| | **Policy No.** | VFX/P2419138 | **Coverage ($)** | 0.00 |
| | **Claim No.** | S3M04L2E | **Excess ($)** | 0.00 |
| | **Assign From** | HO WINNIE | **Assign Date** | 03/04/2023 |

| 2. | Vehicle Particulars & Condition | | | |
|---|---|---|---|---|
| | **Make & Model** | K.T.M. 200 DUKE | **c.c** | 200 |
| | **Engine No.** | HIDDEN | **Year of Reg.** | 2015 |
| | **Chassis No.** | VBKJUC403EC027637 | **Colour** | MULTI COLOUR |
| | **Odometer** | - | **Steering** | IN ORDER |
| | **Brakes** | IN ORDER | **Modification** | SPORTS RIM |
| | **General** | FAIR | | |

| 3. | Conditions of Tyres | | | |
|---|---|---|---|---|
| | | **Size** | **Make** | **Balance** |
| | **R/H Front Tyre** | 110/70 R17 | BRIDGESTONE | 4 mm |
| | **L/H Front Tyre** | | | mm |
| | **R/H Rear Tyre** | 150/60 R17 | BRIDGESTONE | 5 mm |
| | **L/H Rear Tyre** | | | mm |

| 4. | Description of Damages |
|---|---|
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. |

| 5. | General Information | | |
|---|---|---|---|
| | **Accident Date** | 29/03/2023 | **Inspect Date / Time** 04/04/2023 ( 10:06 AM ) |
| | **Survey held at** | JL POWERSPORTS | |
| | | 1 SOON LEE STREET #05-53 PIONEER CENTRE SINGAPORE 627605 | |

| 5a. | Remarks |
|---|---|
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.<br>D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,000-$4,000 |

| 5b. | Estimate Days of Repair |
|---|---|
| | ESTIMATED NORMAL PERIOD FOR REPAIR:              **4 Working Days** |

Report Ref No. CS3/HSB23003456/Rnp3e2

**Inspected By**

*MRB*

**MOHAMMED RASUL BIN MOHD YUNUS**

**Automotive Assessor**

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**