(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/CT/23003891/Ucp3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 30345

at Workshop m/s Ethos Tampines.

of

Insured: GSD178/C

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: $ 50/-

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: 5 days Res.: **Yes** or **No**

Lum Sum: 20 % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS C9436

Vehicle: **IN / OUT**

Date: Person Contacted:

Veh No: GBH 30345 Yr Regn: 13/04/18

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or

Make: Toyota hiace c.c 2982

Colour Black A/C: **Insured / Std / NI / NA**

Sp.Reading T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: JTFHT02P8002422269

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Falken

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	29/03/23	D.O.I.	14/04/23

Survey held at

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or

Rear o/s.

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
1/8/23	Rep 10/- a/s $ 2800 informed Shah h (Ref. 2540/, 47%)

Date/Time, File **Pass** to? ☐ : **Preli. Report**

1) ☑ : **Final Report**

Date/Time, File **Return** to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : TP

Lump Sum / I.B.I: ($ $2800/-)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL