LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL			Ref:	CS3/SMO23004042/Kvy3m4
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Date:	26/04/2023
			Code:	SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SMV 2939J	**Veh. Inspected**	SKS 6709U	
Policy No.	D22MTPV01020860	**Coverage ($)**	0.00	
Claim No.	CMTD2301536/GPL	**Excess ($)**	0.00	
Assign From	IRENE HENRY	**Assign Date**	19/04/2023	

2. Vehicle Particulars & Condition

Make & Model	BMW 316I (A)	**c.c**	1598
Engine No.	HIDDEN	**Year of Reg.**	2015
Chassis No.	WBA3A160X0NS38395	**Colour**	WHITE
Odometer	176173 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	**Make**	**Balance**
R/H Front Tyre	245/35 ZR19	MICHELIN	7 mm
L/H Front Tyre	245/35 ZR19	MICHELIN	7 mm
R/H Rear Tyre	245/35 ZR19	MICHELIN	7 mm
L/H Rear Tyre	245/35 ZR19	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.

5. General Information

Accident Date	15/04/2023	**Inspect Date / Time**	20/04/2023 (02:00 PM)
Survey held at	SOON LEE CHOON AUTO SERVICES BLK 5032 ANG MO KIO IND.PARK 2 #01-283 . SINGAPORE 569535		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $7,000-$9,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	**5 Working Days**

Report Ref No. CS3/SMO23004042/Kvy3m4

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser