# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R




## PRE-REPAIR INSPECTION REPORT

HSBC LIFE (SINGAPORE) PTE LTD

10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983

ATTN: HO WINNIE

Ref: CS3/HSB23004355/Rqp3e2

Date: 15/05/2023

Code: HSB

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | | |
|---|---|---|---|---|
| | **Insured Veh.** | SHC 881M | **Veh. Inspected** | FBR 6106X |
| | **Policy No.** | VFX/P2419140 | **Coverage ($)** | 0.00 |
| | **Claim No.** | S3M04LHP | **Excess ($)** | 0.00 |
| | **Assign From** | HO WINNIE | **Assign Date** | 27/04/2023 |

### 2. Vehicle Particulars & Condition

| | | | | |
|---|---|---|---|---|
| | **Make & Model** | YAMAHA XSR155 MANUAL | **c.c** | 155 |
| | **Engine No.** | HIDDEN | **Year of Reg.** | 2020 |
| | **Chassis No.** | MH3RG4760LK008022 | **Colour** | BLACK |
| | **Odometer** | 25073 KM | **Steering** | IN ORDER |
| | **Brakes** | IN ORDER | **Modification** | SPORTS RIM |
| | **General** | FAIR | | |

### 3. Conditions of Tyres

| | | **Size** | **Make** | **Balance** |
|---|---|---|---|---|
| | **R/H Front Tyre** | 110/70 R17 | BRIDGESTONE | 4 mm |
| | **L/H Front Tyre** | | | mm |
| | **R/H Rear Tyre** | 150/60 R17 | BRIDGESTONE | 4 mm |
| | **L/H Rear Tyre** | | | mm |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.



### 5. General Information

| | | | | |
|---|---|---|---|---|
| | **Accident Date** | 07/04/2023 | **Inspect Date / Time** | 28/04/2023 ( 12:26 PM ) |
| | **Survey held at** | RWAVE PTE LTD<br>50 BUKIT BATOK STREET 23 #02-25 MIDVIEW BUILDING SINGAPORE 659578 | | |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,000-$4,000

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

Report Ref No. CS3/HSB23004355/Rqp3e2

**Inspected By**

MRB

**MOHAMMED RASUL BIN MOHD YUNUS**

**Automotive Assessor**

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**


**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**