# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

HSBC LIFE (SINGAPORE) PTE LTD		Ref:	CS3/HSB23004732/Rvp3m4
10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983		Date:	16/05/2023
ATTN: LOW GARNET		Code:	HSB

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 3042Z	**Veh. Inspected**	FBN 7540P
Policy No.		**Coverage ($)**	0.00
Claim No.	S3M04MCE	**Excess ($)**	0.00
Assign From	LOW GARNET	**Assign Date**	09/05/2023

2. Vehicle Particulars & Condition

Make & Model	YAMAHA CZD300A XMAX300	**c.c**	292
Engine No.	HIDDEN	**Year of Reg.**	2017
Chassis No.	MH3SH081000010163	**Colour**	MULTI
Odometer	56835 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	**Make**	**Balance**
R/H Front Tyre	120/70-15	PIRELLI	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70-14	PIRELLI	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.

5. General Information

Accident Date	05/05/2023	**Inspect Date / Time**	10/05/2023 (04:06 PM)
Survey held at	48 TOH GUAN ROAD EAST #01-112 SINGAPORE 608586		
Repairer	EXCEL CYCLE CENTRE PL		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $2,000-$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

Report Ref No. CS3/HSB23004732/Rvp3m4

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser