LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2304510

INV Date 14/07/2023

Reference CC4/LPC23005124/Rpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBG 2989Z

Insured Veh. YP 7248B

Claim No. 22/23/23/VC05/027393

Policy No. Z22VC05013409

Accident Date 11/05/2023

Inspection Date 19/05/2023

Description	**Total**
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	**350.00**
GST (8%)	**28.00**
Grand Total	**378.00**

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD		Ref:	CC4/LPC23005124/Rpa3q2
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date:	14/07/2023
		Code:	LPC2

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	YP 7248B	**Veh. Inspected**	GBG 2989Z
	Policy No.	Z22VC05013409	**Coverage ($)**	0.00
	Claim No.	22/23/23/VC05/027393	**Excess ($)**	0.00
	Assign From		**Assign Date**	19/05/2023

2.	Vehicle Particulars & Condition			
	Make & Model	NISSAN NV200 1.5 MT	**c.c**	1461
	Engine No.	HIDDEN	**Year of Reg.**	2017
	Chassis No.	VSKYBAM20Z0143510	**Colour**	WHITE
	Odometer	126473 KM	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	NIL
	General	FAIR		

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre	175/70 R14	GRENLANDER	6 mm
	L/H Front Tyre	175/70 R14	GRENLANDER	6 mm
	R/H Rear Tyre	175/70 R14	GRENLANDER	6 mm
	L/H Rear Tyre	175/70 R14	GRENLANDER	6 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	11/05/2023	**Inspection Date**	19/05/2023
	Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR:	**7 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 2989Z

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	FRONT BONNET (N)	TORN	950.00	950.00
1	FRONT BUMPER RETAINER RH (N)	CRACKED	28.00	28.00
1	FRONT BUMPER RETAINER LH (N)	NOT NECESSARY	28.00	-
1	FRONT BUMPER REINFORCEMENT (N)	BENT	1,183.00	1,183.00
1	FRONT BUMPER SPONGE (N)	CRACKED	326.00	326.00
1	FRONT BUMPER TOP GARNISH RHS (N)	DEFORMED	384.00	384.00
10	FRONT BUMPER CLIP @$7.00 (N)	NECESSARY	70.00	70.00
1	FRONT LOGO (N)	NECESSARY	97.00	97.00
1	FRONT GRILLE (N)	CUT	384.00	384.00
4	FRONT GRILLE CLIP @$7.00 (N)	NECESSARY	28.00	28.00
1	FRONT SUPPORT PANEL (N)	TO REPAIR SEE LABOUR	808.00	-
1	INTER COOLER (N)	NOT NECESSARY	2,121.60	-
1	RADIATOR SIDE GARNISH RHS LOWER (N)	DEFORMED	68.00	68.00
8	RADIATOR SIDE GARNISH CLIP @$7.00	NECESSARY	56.00	56.00
1	ALTERNATOR (N)	NOT NECESSARY	1,555.00	-
	LESS 10% DISCOUNT		-808.66	-357.40
			7,277.94	3,216.60
	SPECIAL NETT ITEMS			
6	FRONT BONNET SPONGE CLIP @$7.00 (SN)	NECESSARY	42.00	30.00
1	FRONT FENDER COWLING RHS (SN)	TORN	204.00	204.00
8	FRONT FENDER COWLING RHS CLIPS @$7.00 (SN)	NECESSARY	56.00	30.00
1	FRONT RH HEADLAMP (SN)	CRACKED	684.00	684.00
1	FRONT BUMPER (SN)	DEFORMED	653.00	653.00
1	FRONT BUMPER FOGLIGHT RHS (SN)	CRACKED	340.00	340.00
1	FRONT FOGLIGHT BRACKET LHS (SN)	NOT NECESSARY	105.60	-
1	FRONT BUMPER UNDER COVER (SN)	CRACKED	279.80	279.80
			2,364.40	2,220.80

Report Ref No. CC4/LPC23005124/Rpa3q2

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	LABOUR			
	LABOUR TO JACKING FRONT INNER PANEL,STRAIGHT AND STRAIGHTEN FRONT CHASSIS AND ACCIDENT AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		600.00	550.00
	PUTTY AND SPRAY PAINTING ON AFFECTED AREA FRONT BONNET ,FRONT RH FENDER ,FRONT BUMPER ,INNER PANEL AND OTHER PARTS AFFECTED BY ACCIDENT .		600.00	550.00
			1,200.00	1,100.00
	GRAND TOTAL		**10,842.34**	**6,537.40**

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**5,200.00**

Report Ref No. CC4/LPC23005124/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 2989Z **INSPECTION**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R