Prompt Auto Solutions Pte Ltd
8 Kaki Bukit Avenue 4 #02-37 @ Kaki Bukit (415875)
Tel: 97319322 - Roy Chak
E-mail: promptautosolutions@gmail.com

TP Liberty. Xiao Chen.

TO	:	DATE	:
ATTENTION	:	JOB TYPE	: THIRD PARTY
VEHICLE DETAILS		**ACCIDENT DETAILS**	
VEHICLE NO	: GBE 5895 B	DATE	: 31/05/2023
MAKE / MODEL	: TOYOTA HIACE	TIME	: 17:50 (SGT)
CHASSIS NO	: KDH201-01182712		

S/N	DESCRIPTIONS	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Tailgate Dislodged	1	$ 1,978.00	$ ~~1,978.00~~ 1855
2	Tailgate centre emblem New	1	$ 71.60	$ 71.60
3	Tailgate outer handle New	1	$ 287.00	$ 287.00
4	Tailgate RH number plate lamp Fail	1	$ 58.00	$ 58.00
5	Tailgate LH number plate lamp New	1	$ 58.00	$ 58.00
6	Tailgate inner trim board Torn	1	$ 296.00	$ ~~296.00~~ 165
7	Tailgate inner trim board clips New	1 set	$ 40.00	$ ~~40.00~~ 30
8	Tailgate lock Rust	1	$ 288.00	$ 288.00
9	Tailgate lock catch New	1	$ 54.00	$ 54.00
10	Tailgate weatherstrip Cut	1	$ 387.00	$ 387.00
11	Rear bumper Dented	1	$ 528.00	$ 528.00
12	Rear bumper clip New	1 set	$ 60.00	$ ~~60.00~~ 30
13	Rear bumper RH side retainer New	1	$ 79.00	$ 79.00
14	Rear bumper LH side retainer New	1	$ 79.00	$ 79.00
15	Rear bumper lower brackets New	2	$ 178.00	$ 356.00
16	End panel outer Dented	1	$ 456.00	$ 456.00
17	End panel inner Repair	1	$ 731.00	$ 731.00
18	End panel upper aluminium strip Bent	1	$ 297.00	$ 297.00
19	LH tail lamp assy New	1	$ 315.00	$ 315.00
20	LH tail lamp lower retainer New	1	$ 69.00	$ 69.00
21	RH tail lamp assy Cracked	1	$ 315.00	$ 315.00
22	RhH tail lamp lower retainer New	1	$ 69.00	$ 69.00
			TOTAL PRICE	$ 6,871.60
	4422.60		LIST LESS 20%	$ 1,717.90
	less 25%: 3316.95		**SUB TOTAL PRICE**	**$ 5,153.70**

S/N	DESCRIPTIONS SPECIAL NETT			PRICE	
1	Tailgate windscreen glass sealant	1	$ 80.00	$ ~~80.00~~	40
2	Tailgate windscreen glass inner seal	1	$ 50.00	$ ~~50.00~~	30
3	Tailgate reverse camera	1	$ 600.00	$ 600.00	+
4	Rear number plate	1	$ 70.00	$ ~~70.00~~	50
5	Rear speed limit sticker	1	$ 30.00	$ ~~30.00~~	15
6	Rear bumper reverse sensors	1 set	$ 300.00	$ ~~300.00~~	200
7	End panel (inner) joint seal	1	$ 70.00	$ ~~70.00~~	60
8	Rear bumper clips	1 set	$ 70.00	$ ~~70.00~~	30
	425				
			S/NETT TOTAL	**$ 1,270.00**	

S/N	DESCRIPTIONS			PRICE	
1	Labour charges on affected areas and replaced parts as listed			$ ~~1,200.00~~	800
2	Respray affected areas and parts			$ ~~1,200.00~~	840
3	Check wiring and lighting system & reset eleectronic		1810	$ ~~200.00~~	30
4	Apply anti rust chemical coating			$ ~~200.00~~	60
5	R & R rear W/S glass			$ ~~180.00~~	120
			LABOUR TOTAL	**$ 3,580.00**	
			TOTAL PRICE	**$ 10,003.70**	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L

L/S 06/06/23

06 Days

total: 555.95

L/S: 4 HK