# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

STRIDES AUTOMOTIVE SERVICES PTE LTD	**Ref:** CS3/SMR23006997/Rny3m4
60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705	**Date:** 18/07/2023
	Code: SMR

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHB 5353T	**Veh. Inspected**	GBA 5931B
Policy No.		**Coverage ($)**	0.00
Claim No.	TAX/06/23/2065	**Excess ($)**	0.00
Assign From	HUA YEN	**Assign Date**	10/07/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA 150 M	**c.c**	2982
Engine No.	HIDDEN	**Year of Reg.**	2007
Chassis No.	JTFAT35Y103001336	**Colour**	GREY
Odometer	314178 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	NIL
General	FAIR		

3. Conditions of Tyres

	Size	**Make**	**Balance**
R/H Front Tyre	195R15C	CONDOR	7 mm
L/H Front Tyre	195R15C	CONDOR	7 mm
R/H Rear Tyre	155R12C (D/D)	CONDOR	5/5 mm
L/H Rear Tyre	155R12C (D/D)	CONDOR	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

5. General Information

Accident Date	26/06/2023	**Inspect Date / Time**	11/07/2023 (03:50 PM)
Survey held at	1 PANDAN LOOP #2, SINGAPORE 128219		
Repairer	NEW PIONEER AUTO		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $2,000-$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

Report Ref No. CS3/SMR23006997/Rny3m4

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser