# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL	Ref:	CS3/SMO23007708/Kqy3e2
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623	Date:	02/08/2023
	Code:	SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLX 1878J	**Veh. Inspected**	SBU 1447D
Policy No.	D22MTPV01018825	**Coverage ($)**	0.00
Claim No.	CMTD2302940/BWO	**Excess ($)**	0.00
Assign From	GRACE TEO	**Assign Date**	31/07/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	**c.c**	1794
Engine No.	HIDDEN	**Year of Reg.**	2007
Chassis No.	ZNE100378420	**Colour**	METALLIC BLACK
Odometer	341222 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45Z R17	MICHELIN	7 mm
L/H Front Tyre	225/45Z R17	MICHELIN	7 mm
R/H Rear Tyre	225/45Z R17	MICHELIN	5 mm
L/H Rear Tyre	225/45Z R17	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

5. General Information

Accident Date	24/07/2023	**Inspect Date / Time**	31/07/2023 (02:00 PM)
Survey held at	PEK TIONG AUTO SERVICES		
	BLK 1017 YISHUN INDUSTRIAL PARK A #01-258 SINGAPORE 768759		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,000-$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	**4 Working Days**

Report Ref No. CS3/SMO23007708/Kqy3e2

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser