TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKZ5644S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	?
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	XM
4	ZZ/001	REPAIR RR END PANEL & TAILGATE RENEW RR BUMPER	1075.00	860
5	ZZ/002	S/PAINT RR BUMPER(2TONE),RR END PANEL & TAILGATE	1520.00	1330
		TOTAL LABOUR CHARGES	2925.00	

HONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKZ5644S

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES NETT	LIST	S/NETT	REMARKS
1	SENSOR-REVERSE short	SENSOR			250.00	
2	REAR LICENCE PLATE scr	RLP			60.00	
3	FACE-RR BUMPER torn	85022-4CE0H	849.00			
4	GROMMET($2.2X2) nil	01281-00711			4.40	
5	CLIP($1.5X10) nil	01553-10501	15.00			
6	FINISHER ? X nil	85070-1KA0A	131.00			
7	BRACKET-BUMP LH ? X nil	85221-4CE0A	43.20			
8	BRACKET-BUMP RH ? X nil	85220-4CE0A	43.30			
9	REINF-BUMPER RR ? X nil	85032-4CC0A	663.20			
10	STAY-RH BUMPER ? X nil	H5210-4CCMA	217.90			
11	STAY-LH BUMPER ? X nil	H5211-4CCMA	217.90			
12	WEATHER STRIP X nil	90830-4CC0B	156.80			
13	EMBLEM nil	84890-4CL0A	72.20			
14	EMBLEM nil	84895-4CL0A	122.40			
15	SUNDRIES nil	NPN		20	30.00	
	SUB TOTAL		2531.90	0.00	344.40	
	LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		506.38	0.00	0.00	
	GRAND TOTAL		2025.52	0.00	344.40	
	OVERALL TOTAL		2369.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKZ5644S

TOTAL LABOUR CHARGES	2925.00
TOTAL SPARE PARTS CHARGES	2369.92
GRAND TOTAL	5294.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 91010068
SURVEYED DATE	:	27/08/24
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

5 dmp
Rear bf paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: