Assg. by: REF: CS/INC24080302/Avh3

ASSIGNMENT

From: Date:

Estm Cost:

OD / TPFTNS / TP RES / CD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop/s

of

Insured: YN 1495D

Policy No

Claims No MT/1291177-002

Sum Ensured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SNK6484Z Yr Regn: 2023, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Subaru Forester c.c 1995

Colour Green A/C: Insured / Std / NI / NA

Sp.Reading 27612 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JFISKEKL5NG078137

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18

R: 225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.	17/8/2024	D.O.I.	20/08/24

Survey held at Twin Cars

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP INC
15/11/24	Adrian confirmed LS $7300 (Red 11,528.58, 61%)
	MV :
	PV :
	Nett :

COE Expiry :

Estimate given during : Yes ( ) / 1st Survey : No ( )

Date/Time, File Pass to? 1)

Date/Time, File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

Survey Fee:

Transportation: ___$ + R$ ___$!

Photos

Others

Report Format :