YEW TEE AUTOMOBILE TECH PTE LTD

39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS S(737856)
25 KAKI BUKIT ROAD 4 #01-61 SYNERGY@KB S(417800)

To: ALLIED WORLD INSURANCE

DATE: 04.09.2024

Dear Sir / Madam:

RE: VEHICLE REPAIR ESTIMATE

Owner : MUHAMMAD AZHAR BIN ABDUL RAHIM
Model : TOYOTA CAMRY
Reg : SMS767S Chassis : JTNB23HK203052055 DOAccident : 02.09.2024
THIRD PARTY CLAIM AGAINST

We are please to submit our estimate of repairs to the above mention vehicle.

			Parts	Labour
1	FRONT BUMPER / BR	$	950.00	725 /
2	FRONT BUMPER SIDE RETAINER RH / BR	$	120.00 /	
3	FRONT BUMPER BRACKET RH X AN	$	150.00	
4	FRONT FENDER RH X R	$	585.00	
	Total Parts :	$	1,805.00	
	Less 25%	$	451.25	
		$	1,353.75	

845
-25%
633.75

42	FRONT BUMPER CLIPS (SET)	nec	nett	$ 45.00	30
48	To remove, refix, realign, adjust and replace all damaged parts.			$ 300.00	200
49	TO UNDERCOATING FOR RUST PROTECTION			$ 20.00	10
50	To wrapping accident section.		Bill	$ 600.00	400
				$ 965.00	

Grand Total : $ 2,318.75

640

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

1273.75

Shaun : 97432262

L/S - 1019.00
= 1000

Steve (LKK)
6/9/24, 10.00 am
m R
L/S
L/ M y
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Scanned with CamScanner