Surveyor

REF: CS/TMI24090111/Pqp3

Sherwin

ASSIGNMENT

From: Sherwin Date: 6/9/2024

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess: 3100

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBK 6307U Yr Regn: SEP 2020

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Nissan NV200 1.6A DX c.c 1,597

Colour White A/C: Insured / Std / NI / NA

Sp.Reading NIL T/Radio: Insured / Std / NI / NA

Eng/No: HR16175277D

C/No: VM20160428

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70R14

R: 175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Kapsen

Front		Rear	
R/Bal.	NIL mm	R/Bal.	NIL mm
L/Bal.	NIL mm	L/Bal.	4mm mm

D.O.A. 2/8/2024 D.O.I. 6/9/2024

Survey held at MTM Perofrmance Garage (Toh Guan)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Whole vehicle totally burnt by the fire

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV- 57K
	PARF-15,123K
	NL- 41,877K.
19/09/24	Submit Extensive Total Loss report.
	Investigation $550/-

Date/Time, File Pass to?

1) 19/09 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) ___S + RS___SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format : MER-OD-TL/E

Lump Sum / I.B.I: ($)