LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		

MS INCOME INSURANCE LTD	Ref:	CS/INC24090312/Aqh3e2
75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557	Date:	22/11/2024
	Code:	INC

1.	**Policy Particulars :- THIRD PARTY CLAIM**		
	Insured Veh.	SGU 1272G	Veh. Inspected	SLL 9907U
	Policy No.	-	Coverage	0
	Claim No.	MT/1295624-001	Excess	$0.00
	Assign From	AMANDA	Assign Date	17/09/2024

2.	**Vehicle Details**			
	Make & Model	HONDA HRV	C.C	1496
	Engine No.	L15B4532051	Year of Reg.	17/03/2017
	Chassis No.	JHMRU1810GX202049	Colour	PURPLE
	Odometer	214626 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		

3.	**Conditions of Tyres**			
		Size	**Make**	**Balance (mm)**
	R/H Front Tyre	215/60 R16	PRIN	6
	L/H Front Tyre	215/60 R16	PRIN	6
	R/H Rear Tyre	215/60 R16	PRIN	6
	L/H Rear Tyre	215/60 R16	PRIN	6

4.	**Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5.	**General Information**		
	Accident Date	15/09/2024	Inspection Date	18/09/2024 (15:59)
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a.	**Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	**Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days