

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

MS FIRST CAPITAL INSURANCE LIMITED
 16 RAFFLES QUAY #42-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department

Contact : 65073848 Fax No. : 65073849

Not Authorised
11/12/2024
Resurvey After Repair
5 days

Estimate : TP24/028

Date : 04/10/2024
 Vehicle Num. : SGY 4673S
 Make/Model : TOYOTA ALTIS-2007
 Chassis/Eng# : MR053ZEC107154129/3ZZ4691850
 Accident Date : 30/09/2024
 Claim No. : D24008620MFCT
 Reference : LYB/SGY4673S/FirstCap/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER	70.20	70.20
2.	2	REAR BUMPER BRACKETS	30.20	60.40
3.	2	REAR BUMPER RETAINER	80.80	161.60
4.	1	REAR LID	49.20	49.20
5.	1	REAR LID RUBBER		98.40
6.	2	REAR LID HINGES		90.70
7.	1	REAR LID LOCK (UPPER)		42.10
8.	1	REAR LID LOCK (LOWER)		666.10
9.	1	REAR TAILEND PANEL	54.20	54.20
10.	2	REAR TAILEND PANEL TEROSTAT SEALANT		108.40
11.	1	REAR TAILEND INNER GARNISH		45.15
12.	1 SET	REAR TAILEND INNER GARNISH CLIPS		12.00
13.	1	REAR EMBLEM '1.6E'		40.20
14.	1	REAR EMBLEM 'VVTI'		39.70
15.	1	REAR EMBLEM 'COROLLA'		51.30
16.	1	REAR EMBLEM 'ALTIS'		40.20
17.	2	REAR TAILLAMP ASSY	311.70	623.40
18.	2	REAR TAILLAMP LOWER PANEL	121.60	243.20
19.	1	REAR REFLECTOR ASSY		70.20
20.	12	REAR RIVET	2.80	33.60
21.	1	REAR SILENCER		666.70
22.	1	REAR SPARE TYRE PANEL		931.60
23.	1	REAR BUMPER LIP SPOILER		551.30
24.	1	REAR BOOT LID OUTER HANDLE		185.10
List TotalS\$:				6,045.25
25.00% Discount S\$:				1,511.31
				4,533.94

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

MS FIRST CAPITAL INSURANCE LIMITED
 16 RAFFLES QUAY #42-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP24/028

Date : 04/10/2024
 Vehicle Num. : SGY 4673S
 Make/Model : TOYOTA ALTIS-2007
 Chassis/Eng# : MR053ZEC107154129/3ZZ4691850
 Accident Date : 30/09/2024
 Claim No. : D24008620MFCT
 Reference : LYB/SGY4673S/FirstCap/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1 set	NETT ITEMS : REAR REVERSE SENSOR		220.00
		Nett Total S\$:		220.00
		10.00% Discount S\$:		22.00
				198.00
1.	1	SPECIAL NETT ITEMS : REAR BUMPER LIP SPOILER SEALANT	10.00	54.20
2.	5	REAR BUMPER FASTER	10.00	50.00
3.	5	REAR BUMPER EXTENSION FASTER	10.00	50.00
4.	5	REAR BUMPER EXTENSION GROMMET SCREW	10.00	50.00
5.	1	REAR SPARE TYRE PANEL TELOSANT SEALANT		54.20
				258.40
		Special Nett Total S\$:		
		LABOUR :		180.00
		TO REMOVE,CHECK & REPAIR/REPLACE EXHAUST SILENCER		120.00
		LABOUR TO REPLACE THE SENSOR & CHECK WIRING FUNCTIONS		150.00
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS		80.00
		TO TRANSFER BOOT LID PARTS & FITTING TO NEW BOOT LID		

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

MS FIRST CAPITAL INSURANCE LIMITED
 16 RAFFLES QUAY #42-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP24/028

Date : 04/10/2024
 Vehicle Num. : SGY 4673S
 Make/Model : TOYOTA ALTIS-2007
 Chassis/Eng# : MR053ZEC107154129/3ZZ4691850
 Accident Date : 30/09/2024
 Claim No. : D24008620MFCT
 Reference : LYB/SGY4673S/FirstCap/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CHECK WATER SEEPAGE		80.00 <i>2d</i>
		TO REPAIR,PANEL BEAT, CUT & WELD ON AFFECTED PANEL & LABOUR TO REPLACE ABOVE PARTS.		1,000.00 <i>60d</i>
		TO PUTTY,PRIMER & SPRAY PAINT ON REAR BOOT LID,LID SPOILER,PANEL,SPARE TYRE PANEL,BUMPER,BUMPER SPOILER, TAILLAMP LOWER PANEL & REAR REVERSE SENSOR.		1,500.00 <i>80d</i>
				<u>3,110.00</u>
		Labour Total S\$:		

E. & O.E.

Total S\$: 8,100.34

for LIM YEW BOO SPRAY PAINT CO.