LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS MS FIRST CAPITAL INSURANCE LTD		Ref:	CS/FCI24100102/Unp3
16 RAFFLES QUAY		Date:	14/10/2024
#42-01 HONG LEONG BUILDING			
SINGAPORE 048581		Code:	FCI2

1.	**Policy Particulars :- THIRD PARTY CLAIM**			
	Insured Veh.	SH 9922M	**Veh. Inspected**	SMT 2963Z
	Policy No.	D-24101861MFCT	**Coverage**	0
	Claim No.	D24008667MFCT	**Excess**	$0.00
	Assign From	HARMINDER	**Assign Date**	03/10/2024

2.	**Vehicle Details**			
	Make & Model	MAZD 3 (A)	**C.C**	1496
	Engine No.	P520330328	**Year of Reg.**	24/11/2015
	Chassis No.	JM6BM42A8G0324493	**Colour**	SILVER
	Odometer	116071 KM	**Steering**	IN ORDER
	Brakes	IN ORDER	**General**	GOOD
	Modification(s)	RIMS: SPORTS RIM		

3.	**Conditions of Tyres**			
		Size	**Make**	**Balance (mm)**
	R/H Front Tyre	205/60R16	YOKOHAMA	6
	L/H Front Tyre	205/60R16	YOKOHAMA	6
	R/H Rear Tyre	205/60R16	YOKOHAMA	6
	L/H Rear Tyre	205/60R16	YOKOHAMA	6

4.	**Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5.	**General Information**			
	Accident Date	01/10/2024	**Inspection Date**	04/10/2024
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a.	**Remarks**

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	**Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days