REF: CS/INC24100131/Aqh3

ASSIGNMENT

From: Date:	Veh No: SXS8837J Yr Regn: 2018 Oct.
Estn Adjust:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
OD / TP / TP RES / CD RES / EVA / INV / MV	
To Insd Vehicle No:	Make: Land Rover Range Rover C.C 2995
at Wkshop/s	Colour: Black A/C: Insured / Std / NI / NA
of	Sp.Reading: 91708 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No	C/No: SALGA2AV3JA501356
Claims No	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 295/40R22
(Policy Condition)	R: 295/40R22
Remark: The veh had commenced its repair at the time of inspection. N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental
Bal. or Market Value:	Front / Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs 3 days Res.: Yes or No	D.O.A. D.O.I. 08/10/24.
Lum Sum: % 3 Val.: Yes or No	Survey held at Hua Mey
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP INC
	COE Expiry
	LS $5600, 3 days (Red $5792.12, 51%)
	Estimate given during 1st Survey: Yes (✓) No ( )
	MV:
	PV:
	Nett:

Date/Time, File Pass to? [ ]: Preli. Report

1) 08/11 Typist [ ]: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: [ ]: Site Insp ($) [ ]: Interview ($) [ ]: Tech. Inve ($) [ ]: ...

Survey Fee:	
Transportation:	
$ + R$ ___ $I	
Photos	
Others	

Report Format: TP