COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD3070L

Make : BYD

Model : NEW E6

Date: 25/10/2024

Insurance: ECICS

MVA MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	FRONT HATCH ASSEMBLY X R			$ 1,976.00	
1	FRONT GRILLE ASSEMBLY / CRA			$ 585.00	/
1	FRONT BUMPER BODY ASSY X nn			$ 1,010.00	
	SUB TOTAL			$ 3,571.00	
	LESS 20%			$ 714.20	
	DISCOUNTED TOTAL			$ 2,856.80	468
				$ -	
	Labour Charge				
	PANEL BEATING			$ 500.00	450
	SPRAY PAINTING CHARGE			$ 950.00	450
	TOTAL LABOUR			$ 1,450.00	
	ESTIMATE TOTAL			$ 4,306.80	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1368

Steve (LKK)
25/10/24, 3.00pm
m IL
P/P
4 BL 4
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CamScanner