Accident Repair Estimate

ENT DATE:	27-Oct-24	BUS NUMBER:	SG6047P
ACCIDENT TIME:	1350Hrs	BUS MODEL:	WDD
ACCIDENT REPORT NUMBER:	AR-2024-5881	DATE OF SURVEY:	1-Nov-24
3RD PARTY CLAIM AGAINST :	XE9237P		

SECTION A : PARTS & MATERIAL COST

Part or Item Description	Quantity	Total Cost
MIRROR ARM COMPLETE W/MIRROR.N/S.E5/6	1	$991.00
STKR;3M SCOTCHLITE FLUOR DIAMOND GRD	1	$2.00
	TOTAL PARTS & MATERIAL CO	$993.00

SECTION B: ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)

To Remove / Replace / Repair Damaged Parts by Workshop	$188.00
To Remove / Replace / Repair Damaged Parts by Contractor	$0.00
To Remove/ Replace/ Repair Damaged Advertisement Panel	$0.00
TOTAL LABOUR COST	$188.00

SECTION C: SUMMARY

Total Repair Costs		$1,181.00
Total Downtime (Days)	1	$458.52
Towing Cost		$0.00
Total Overheads Costs		$354.30
	TOTAL COST	$1,993.82

*Please kindly note that the downtime (days) is just an estimate.
*Please undersign to acknowledge this repair estimate.

Prepared by: ERIC NG
Snr Technical Officer
Ulu Pandan Workshop
Bus Engineering

Signature:

Date: 1/11/24

Surveyor Name & Contact: Rasul - Hp 90010068

Signature :

Date: 01/11/24 / 1 day

Reg after repair

993.00
188.00
1181.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: