REF: CS/CTI24110142/Aqh3

ASSIGNMENT

From: Date:

Estim Cost:

OD / TPFT / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKC3006B Yr Regn: 2019, March.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or AMG C63S

Make: Mercedes Benz C.C 3982

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 38513 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2053872F854057

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/35R19

R: 255/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	08/11/24

Survey held at Adviene

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP China. COE Expiry:
	LS $3400, 3 days (Red $2137.20, 39%)
	Estimate given during: Yes ( )
	MV: 250K 1st Survey: No (✓)
	PV: 149.3K
	Nett: 100.7K
	3007.

Date/Time, File Pass to? ☐: Preli. Report ☐: Final Report

1) 17/03 Typist

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: ☐: Site Insp ($) ☐: Interview ($) ☐: Tech. Inve ($)

Survey Fee:

Transportation: __$ + R$__$

Photos

Others

Report Format: EZCLAIMS-TP