Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J liusbro@ymail.com
Tel: 67411730

ESTIMATE

Name: ECICS Limited
Addres: Motor Claims Department
10 Eunos Road 8 #09-04A
Singapore Post Centre Singapore 408600

Ref Date: 06-07-2023
Ref No: YP4641T260626
Vehicle No: YP4641T
Model / Make: Mitsubishi Canter
Capacity: 2998 cc FEB71ER4SDEC (CBU)

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	~~Rear Rh~~	Cargo Box Sliding Door lock o/s	$ 280.00	1	$ 280.00	SN	RX
2		Cargo Box Sliding Door front piller o/s	$ 1,400.00	1	$ 1,400.00	SN	CRO 1200 S/N
3		Step Panel	$ 400.00	1	$ 400.00	SN	RX
4		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs			$ 600.00		580
5		To putty & spray painting & including touch up paint on accident affectecd areas			$ 600.00		500
6		To apply Rust Proofing , reseal tuff-coating treatment on accident area			$ 50.00		NNX

Total Parts & Labour of estimate for damaged vehicle	$ 3,330.00	
Total amount in Lumpsum Basis for repaired vehicle		$ -

SDL

Liu's Bro Auto Engrg Wks

P-1200 S/N
L 1080
2280
202
1824

Not Authorised
LKK
7/7/23
d/s $1800
4 days.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Firm's prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: