LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		
MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24060046/Unp3m4
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Date:	12/06/2024
	Code:	AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 9814B	**Veh. Inspected**	YQ 6134Y
Policy No.	P10882880R01	**Coverage**	0
Claim No.	C10029807/HY	**Excess**	$0.00
Assign From	MICHAEL	**Assign Date**	12/06/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA 150 (M)	**C.C**	2755
Engine No.	1GD8882729	**Year of Reg.**	22/03/2022
Chassis No.	JHHAGV4640K001911	**Colour**	SILVER
Odometer	112169 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**General**	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	175/75R15	BRIDGESTONE	3
L/H Front Tyre	175/75R15	BRIDGESTONE	3
R/H Rear Tyre	155R13 (D)	YOKOHAMA	7
L/H Rear Tyre	155R13 (D)	YOKOHAMA	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/06/2024	**Inspection Date**	13/06/2024
Survey held at	FOCUS AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #02-50 KAKI BUKIT @ AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days