ASS. REC. BY:

REF: CS/MSG 17018938 / Tltbm2 Special Instruction:

Surveyor: Taufikh.
Meimen

ASSIGNMENT (Office)

From (Person): Lionel Tan of MSIG Date/Time: 3/10/17 1:33pm

Estimated Cost: Bill to:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLF 6121 X Insured: SCH 9111 B

at Workshop m/s: Performance Motor Tel: 63190174

of: 303 Alexandra Road, 159941

Policy No:

Claim No: 531587

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 2/10/2017

CA / REV / REP. / REV 24 HRS 'wp' 10.10.2017

H.O.D. Endorsement:

Date/Time: 3/10/17 2:00pm Person Contacted: Caroline Vehicle IN / (OUT)

Date/Time	Action/Instruction
	(✓) Estimate Chua
	SLF6121X – X
	SCH 9111B – X
	Confirm $3,212.40. 3days. (Red: 3569.20: 52%)

Est. Repairs ______ days Res: Yes or No

Lum Sum ______ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: Person Contacted: Chua. Vehicle IN / OUT

Date / Time Action / Instruction

D.O.A. 6 mm

D.O.I. 10/10/17 @10am 6 mm

Survey held at: PML

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

[signature]

12/2/2018

RECEIVED 12 FEB 2018

Date/Time File Pass to?: 6/2 Typist.

Date/Time File Return to?:

[ ] : Preli. Report

[✓] : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

[ ] Site Insp (S$

[ ] Interview (S$

[ ] Tech Invs (S$

[ ] Weekend (S$

Report Format: TP

Lump Sum / (I.B) I: (S$ 3212.40)

Survey Fee	
Transportation	
S-RS (S$	200
Photos	10
Others	
TOTAL	210