ask for S.pp's part prices.

ASS REC. BY: | REF: CS/AXA 17021555/Agbe2 | Special Instructions:

Surveyor: Adrian

Menmen

ASSIGNMENT (Office)

From (Person): Yvonne Ang of AXA Date/Time: 10/11/17 @ 11.43am

Estimated Cost: Bill to:

(OD) / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFA 6116 J Insured:

at Workshop m/s: Auto Germany Tel: 6511 3025 / 82988933

of 23, kaki Bukit Ave 4 # 04-01, 415933

Policy No: P1994168 Claim No: C0458832

Sum Insured: Excess: $750.00

Make of Veh: (Client's Record) D.O.A. 3/11/2017

(CA) / REV / REP. / REV 24 HRS

Date/Time: 2.02pm @ 10/11/17 Person Contacted: Suheimi H.O.D. Endorsement: Vehicle (IN) / OUT

Date/Time	Action/Instruction (✓) Estimate
	SFA 6116J - S.P. / INC17021116 / B3 DOA: 03/11/17
13/11/17@2.54pm	revised to Yvonne Ang via Menmen.
30/11/17@9.54am	2nd revised to Yvonne Ang via Menmen. (supplementary).
26/12/17@1.48pm	confirmed with Kelvin final fig $ 19098.85, 8 days. (Red $ 6755.10, 75%)
06/1/18@10pm	Kitty Teo informed that they have received invoice from supp. ask us to submit our report

Surveyor | REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: 115K.

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: 8 days Res.: **Yes** or **No**

Lum Sum: % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: Person Contacted:

Veh No: SFA6116 J. Yr Regn: 2014 / Sept

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or

Make: Opel Cascada. c.c 1598.

Colour Black A/C: **Insured / Std / NI / NA**

Sp.Reading 28605. T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: WOLWT3D34EG008459

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 235/50 R18

R: 235/50 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	10/11/17.

Survey held at Auto Germany.

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	OD AXA.

RECEIVED

Date/Time, File **Pass** to?

1) 08/1 [illegible]

Date/Time, File **Return** to?

2)

☐ : **Preli. Report**

☐ : **Final Report**

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee: 300

Transportation:

Add Fee:

☐ : Site Insp ($) ___S + RS, ___SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL 300

Report Format : MER-OD

Lump Sum / I.B.I: ($ 19098.85)

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Ref : CS/AXA17021555/Aqb

Date : 13-11-2017

Code : AXA2

1. Policy Particulars :- OWN DAMAGE

	Insured Veh.		**Veh. Inspected**	SFA 6116J
	Policy No.	P1994168	**Coverage ($)**	0.00
	Claim No.	C0458832	**Excess ($)**	750.00
	Assign From	MERIMEN (YVONNE ANG)	**Assign Date**	10/11/2017

2. Vehicle Particulars & Condition

	Make & Model		**c.c**	0
	Engine No.	HIDDEN	**Year of Reg.**	
	Chassis No.		**Colour**	
	Odometer	-	**Steering**	
	Brakes		**Modification**	
	General			

3. Conditions of Tyres

		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4. Description of Damages

5. General Information

	Accident Date	03/11/2017	**Inspection Date**	10/11/2017
	Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933		

5a. Remarks

A)THE MARKET VALUE IS S$----------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No.: CS/AXA/7071555/Ang
Policy Type: OD / TP / TP RES / TL / EVA

SFA 6116J

Admin (Cathy): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

		Case Handler Y-Date	Case Handler N-Date	Typist Y-Date	Typist N-Date
(1) Office Assign Form					
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (Adrian): Case handler to make sure the surveryor completed all required information.

		Case Handler Y-Date	Case Handler N-Date	Typist Y-Date	Typist N-Date
(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			
(2) System - (Views/Merimen)					
C	Damaged Vehicle Photographs Uploaded	✓			
(3) Workshop Estimate/Assignment Form					
N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				
(4) System - (Views/Merimen)					
C	Resurvey photo Uploaded	✓			

Check By: [signature] 26/12/17
Case Handler Date

*C: Critical *N: Non-Critical

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Est Appr'd	Status
Main	10 Nov 2017		10 Nov 2017 11:43 Assign				**New Assignment** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**LIM SWEE HOE**, ID: S1675020D, Tel: +6597500065, Email: BDSA11@YAHOO.COM		
Vehicle Reg. No.:	**SFA6116J**	Date of Loss:	03/11/2017 15:00 - :59
Claim Type:	**OD** / C0458832	Policy/Cover Note No.:	P1994168 (Comprehensive)
		Excess:	S$750.00
Repairer:	**Auto Germany Pte Ltd (HQ)** 7 Ubi Close,, Apline Centre, 408604 Kaki Bukit - Tel: 6511 3025		
Handling Insurer:	**AXA Insurance Pte Ltd (Non-APW)** - Tel: ... [Handled by **Yvonne Ang Ching Ching** - 6880 4461]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Final Rpt** due 21/11/2017]		
Driver/Custodian:	LIM SWEE HOE (), NRIC: S1675020D, Tel: +6597500065		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

SG AXA Insurance SM AXA SGP - Motor Survey

From: Vincent Sim <vincent.sim@alpinemotors.sg>
Sent: Thursday, November 09, 2017 4:53 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: suhaimi@alpinemotors.sg; Kelvin Chew
Subject: SFA6116J- OPEL CASCADA OWN DAMAGE CLAIM - AXA
Attachments: Estimate.pdf; SFA6116J.PDF

Categories: Santosh

Dear Sir,
Attached are the estimate and reporting for the above for your survey,

Person in charge ;-
Suhaimi
H/p 8298-8933
Kelvin
H/p 8292-5595

E-mail ;
suhaimi@alpinemotors.sg

Add;
1st autoworks pte ltd
23, kaki bukit ave 4
#04-01 (south wing)
singapore 415933
(vicom building)
tel; 6844-1985

Regards,
Vincent Sim- Claims Dept

vincent.sim@alpinemotors.sg

65113022 ext 343

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 26 December, 2017 1:48 PM
To: 'Kelvin.chew@alpinemotors.sg'; SUR
Subject: RE: SFA 6116 J OPEL CASCADA AXA OD DOA 03.11.2017

Dear Kelvin,

Confirm final fig $19,098.85 before excess $750.00 & GST and 8 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Wishes you a Merry Christmas & Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kelvin Chew [mailto:Kelvin.chew@alpinemotors.sg]
Sent: Friday, 8 December, 2017 8:22 PM
To: SUR <sur@lkkauto.com>
Cc: suhaimi@firstautoworks.com.sg
Subject: SFA 6116 J OPEL CASCADA AXA OD DOA 03.11.2017

Hi Lkk,

attach is finalize calculation.
part by part $19,098.85 before excess $750.00 @ 8 working days.
kindly please check & confirm with me.
thanks.

from,
kelvin chew
8292 5595

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kitty Teo

Date: 30 Nov 2017

Preliminary Advice

Vehicle No	: SFA6116J	Accident Date	: 03/11/2017
Make	: OPEL CASADA	Policy No.	: P1994168
Assignment Date	: 10/11/2017	Excess	: S$750.00
Date of Inspection	: 10/11/2017	Est. Duration of Repair	: 8.00
Inspection At	: AUTO GERMANY PTE LTD (HQ) 7 UBI CLOSE,, APLINE CENTRE SINGAPORE 408604		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	25,353.95	(ESTIMATE $24,608.95 + SUPPLEMENTARY $745.00)
Revised Amount	:S$	16,206.05	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S$	3,252.60	
Total	:S$	19,458.65	
Lump Sum Repair	:S$		

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	115,000.00
COE / PARF Rebate	:S$	82,313.00
Salvage Value	:S$	
Margin for Repair	:S$	32,687.00

Remarks

(X) The vehicle is repairable at our adjusted amount.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : We have received supplementary of $745.00 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Yvonne Ang Ching Ching

Date: 13 Nov 2017

Preliminary Advice

Vehicle No	: SFA6116J	Accident Date	: 03/11/2017
Make	: OPEL CASADA	Policy No.	: P1994168
Assignment Date	: 10/11/2017	Excess	: S$750.00
Date of Inspection	: 10/11/2017	Est. Duration of Repair	: 8.00
Inspection At	: AUTO GERMANY PTE LTD (HQ) 7 UBI CLOSE,, APLINE CENTRE SINGAPORE 408604		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	24,608.95
Revised Amount	:S$	15,461.05
Check Items (Estimated)	:S$	3,252.60
Total	:S$	18,713.65
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	115,000.00
COE / PARF Rebate	:S$	82,313.00
Salvage Value	:S$	
Margin for Repair	:S$	32,687.00

Remarks

(X) The vehicle is repairable at our adjusted amount.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : WE HAVE AUTHORISE REPAIR ON 10/11/2017 AT 4.38pm.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	5020D

Vehicle Details

Vehicle No.	SFA6116J
Vehicle to be Exported	No
Intended De-registration Date	13 Nov 2017
Vehicle Make	OPEL
Vehicle Model	CASCADA
Primary Colour	Black
Manufacturing Year	2013
Engine No.	B1131983B7GX0002
Chassis No.	W0LWT3D34EG008459
Maximum Power Output	125.0 kW (167 bhp)
Open Market Value	$36,663.00
Original Registration Date	10 Sep 2014
First Registration Date	10 Sep 2014
Transfer Count	1
Actual ARF Paid	$43,329.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	09 Sep 2024
PARF Rebate Amount	$32,496.00

Intended COE Rebate Details

COE Expiry Date	09 Sep 2024
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	$73,010.00
COE Rebate Amount	$49,817.00
Total Rebate Amount	**$82,313.00**

The information contained herein is correct as at 13 Nov 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	03/11/2017 17:29
Date Of Accident	03/11/2017 15:15
Exact Location Of Accident	ANAK BUKIT FLYOVER TOWARDS BUKIT TIMAH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFA6116J
Insured/Policyholder	
Name Of Registered Owner	LIM SWEE HOE
NRIC No	S1675020D
Email Address	BDSA11@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97500065
Alternative Phone No	OFFICE-97500065
Vehicle Particulars	
Manufacturer	OPEL
Model	CASCADA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1994168
Cover Note Number	
Driver	
Name of Driver	LIM SWEE HOE
NRIC No	S1675020D
Date Of Birth	22/05/1964
Occupation	INDOOR
Date Of Driving Pass	21/01/1982
Driving Experience	35 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97500065
Fax Number	
Contact Number	OFFICE-97500065
EMail Address	BDSA11@YAHOO.COM

Address	144 , 15-02 UPPER BUKIT TIMAH ROAD
Postcode	588177
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO ATTACHED REPORT AND PHOTOS ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD8304R
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	XU JIANFENG
NRIC/Passport Number	
Contact Number	90217427
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was exiting PIE into VPP at 1 mph & on the left lane. The Truck on my right swerve into my lane to avoid a oncoming bus. Refer to sketch.
I honed repeatly but he did not stop. This case his truck to hit me badly on the right front of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

INSURANCE

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel:(65)63367288 Fax (65)63382522
Website:www.axa.com.sg
GST Registration Number: 199903512M
customer.services@axa.com.sg

CERTIFICATE OF INSURANCE

*Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) *Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 *Road Transport Act, 1987 (Malaysia) *Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO.	: **VPA/P1994168**	Account No. : **15038**
Coverage	: **Comprehensive**	
Sum Insured	: **Market Value At The Time Of Loss**	
Name of Policy Holder	: **LIM SWEE HOE**	
Vehicle Registration No.	: **SFA6116J**	
Period of Insurance	: From **22/07/2017** To **09/09/2018** (Both Dates Inclusive)	

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

(a) The Policyholder
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner
(b) Any other person who is driving on the Policyholder's order or with his permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover : use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess : **SGD 750.00**

An Additional Excess is applicable as follows:
S$500.00 for Unnamed Authorized Driver &/or Declared Young & Inexperienced Driver.
S$5,000.00 for Undeclared Young and Inexperienced Driver.
(Please refer to your policy on the terms & conditions)

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 96 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - **SGRAC01** on **27/09/2017**

IMPORTANT
Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the Insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap 189).
The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

LICENSE

IC



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1675020D

Name

LIM SWEE HOE

林瑞河

Race

CHINESE

Date of Birth

22-05-1964

Sex

M

Country of Birth

SINGAPORE

IC AND DRIVING LICENSE



Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
5 Raffles Quay #35-10 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours Monday to Friday, 09.00 17.00
UEN: S68SS0020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the **same** Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MAUA17145604 Vehicle Registration No: SBA 6116J

Name (as shown in NRIC) : Lim Jin Ee Thye NRIC/FIN/Passport No : S1677020D

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

Address : _____ Singapore( )

Contact (Tel) : _____ Mobile No. : _____

Email Address : _____

Date of Accident : _____ Time of Accident : _____

Place of Accident : _____

Insurance Company : (AXA)

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

"to Convert from 3rd Party to Our Damaged claim"

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: Lee Se-Ee
NRIC/FIN No.:
Date: 05/09/2017

AUTO GERMANY PTE LTD

Repair Estimate

Date :09/11/2017

Reference: OPEL Weil Ueben Autos.
Make: CASCADA

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SFA6116J
CHASSIS NO.: W0LWT3D34EG008459
ENGINE NO.: B1131983B7GX0002

Name of insured .: LIM SWEE HOE
Date of accident.: 03/11/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description		Price (SGD)	
1	1	FRT BONNET Rpir		$ 1,843.00	
2	1	FRT WINDSCREEN OUTER MLDG RH Dented		$ 303.00	
3	1	FRT QUARTER GLASS ASSY RH Cut		$ 871.00	
4	1	FRT BUMPER Distorted		$ 2,027.00	
5	1	FRT BUMPER TOW COVER New		$ 81.00	
6	15	FRT BUMPER CLIP New		$ 97.50	
7	1	FRT BUMPER SIDE RETAINER LH New		$ 150.00	
8	1	FRT BUMPER SIDE RETAINER RH Rpd		$ 150.00	
9	1	FRT BUMPER BRACKET LH New		$ 180.00	
10	1	FRT BUMPER BRACKET RH Rpd		$ 180.00	
11	1	FRT BUMPER BRACKET TOP CENTRE New		$ 267.00	
12	1	FRT BUMPER SPONGE Cracked.		$ 324.00	
13	2	FRT BUMPER PARKING SENSOR 1 piece dmgd		$ ~~350.00~~	175
14	2	FRT BUMPER PARKING SENSOR SEAL 1 piece dmgd		$ ~~24.00~~	12
15	1	FRT BUMPER PARKING SENSOR WIRE HARNESS Cracked		$ 487.00	
16	1	FRT GRILLE New New		$ 870.00	
17	1	FRT GRILLE LOGO New		$ 98.00	
18	1	RH HEADLAMP Smashed		$ 1,660.00	
19	1	RH FOG LAMP Cracked		$ 293.00	
20	1	RH FOG LAMP COVER Missing		$ 185.00	
21	10	FENDER INNERSHIELD CLIP New		$ 65.00	
22	1	FRT FENDER RH Distorted		$ 531.00	
23	1	FRT FENDER SIGNAL LAMP RH New		$ 188.00	
24	1	FRT FENDER INNERSHIELD RH Dented		$ 207.00	
25	1	FRT DOOR RH Distorted		$ 2,691.00	
26	1	FRT DOOR HINGE UPP RH New		$ 185.00	
27	1	FRT DOOR HINGE LOW RH New		$ 185.00	
28	1	FRT SHOCK ABSORBER RH Bent		$ 311.00	
29	1	FRT KNUCKLE ARM RH Bent		$ 600.00	

Auto Germany Pte Ltd
7 Ubi Close, Alpine Centre
Singapore 408604

Sales Tel: 6922-3288 Fax: 6922-3289
Service Tel: 6922-3282 Fax: 6922-3283
Parts Tel: 6922-3285 Fax: 6922-3286

Opel Passenger and Commercial Vehicles

Email: enquiry@autogermany.sg
Web: opel.com.sg

30	1	FRT WHEELBEARING RH Bent New		$ 657.00	2
31	1	FRT LOW ARM RH Bent		$ 968.00	2
32	1	FRT RIM RH cut		$ 937.00	1

Parts Total: $ 17,965.50
Less10%: $ 1,796.55
Total : $ 16,168.95

Labour

Labour Description

No.			Price (SGD)	
1		To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts.	$ ~~3,250.00~~	1850
2		Carry out spray painting on affected area, FRT BUMPER, FRT RH FENDER, FRT SUPORT PANEL, FRT BONNET, FRT RH DOOR	$ ~~2,750.00~~	2200
3		To disconnect wire harness of electrical component to facilitate repairs,reconnect and check electrical function after repair	$ ~~220.00~~	180
4		To remove and replace RHF under carriage parts	$ 650.00	1
5		To conduct 4 wheel alignment	$ ~~220.00~~	180
6		To conduct reset of ABS light on	$ 350.00	1
7		To conduct transfer front door mechanism to new door panel	$ ~~650.00~~	325

Labour Total : $ 8,090.00

Others

Other Description

No.				Price (SGD)	
1		FRT TYRE RH Punctured		$ ~~350.00~~	280
2					

Other Total: $ 350.00

TOTAL: $ 24,608.95
GST (7%): $ 1,722.63

GRAND TOTAL : $ 26,331.58

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

25279.43

Yours faithfully

Adrian
P/? 10/11/17

Excess $750.

~~Cos~~ Authorised Repairs.

08 Days

Service Advisor

SUPPLEMENTARY
VEHICLE NO: SFA 6116 J

QTY	PARTS DESCRIPTION	PRICE
1	Frt Absorber Connectors Arm RH Bent ✓	483
1	Air Intake insulator box cracked ✓	262

AUTO GERMANY PTE LTD

Repair Estimate

Date :09/11/2017

Reference: OPEL Meuleben Autos.
Make: CASCADA

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SFA6116J
CHASSIS NO.: W0LWT3D34EG008459
ENGINE NO.: B1131983B7GX0002

Name of insured .: LIM SWEE HOE
Date of accident.: 03/11/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description		Price (SGD)	
1	1	FRT BONNET Repair		$ 1,843.00	
2	1	FRT WINDSCREEN OUTER MLDG RH Damaged		$ 303.00	
3	1	FRT QUARTER GLASS ASSY RH Cut		$ 871.00	
4	1	FRT BUMPER Distorted		$ 2,027.00	
5	1	FRT BUMPER TOW COVER New		$ 81.00	
6	15	FRT BUMPER CLIP New		$ 97.50	
7	1	FRT BUMPER SIDE RETAINER LH New		$ 150.00	
8	1	FRT BUMPER SIDE RETAINER RH Damaged		$ 150.00	
9	1	FRT BUMPER BRACKET LH New		$ 180.00	
10	1	FRT BUMPER BRACKET RH Damaged		$ 180.00	
11	1	FRT BUMPER BRACKET TOP CENTRE New		$ 267.00	
12	1	**FRT BUMPER SPONGE** Cracked		$ 324.00	
13	2	FRT BUMPER PARKING SENSOR 1 piece damaged		$ ~~350.00~~	175
14	2	FRT BUMPER PARKING SENSOR SEAL 1 piece damaged		$ ~~24.00~~	12
15	1	**FRT BUMPER PARKING SENSOR WIRE HARNESS** Cracked		$ 487.00	
16	1	FRT GRILLE New		$ 870.00	
17	1	FRT GRILLE LOGO New		$ 98.00	
18	1	RH HEADLAMP Smashed		$ 1,660.00	
19	1	RH FOG LAMP Cracked		$ 293.00	
20	1	RH FOG LAMP COVER Missing		$ 185.00	
21	10	FENDER INNERSHIELD CLIP New		$ 65.00	
22	1	FRT FENDER RH Distorted		$ 531.00	
23	1	FRT FENDER SIGNAL LAMP RH New		$ 188.00	
24	1	FRT FENDER INNERSHIELD RH Bent		$ 207.00	
25	1	FRT DOOR RH Distorted		$ 2,691.00	
26	1	FRT DOOR HINGE UPP RH New		$ 185.00	
27	1	FRT DOOR HINGE LOW RH New		$ 185.00	
28	1	**FRT SHOCK ABSORBER RH** Bent		$ 311.00	
29	1	**FRT KNUCKLE ARM RH** Bent		$ 600.00	

Auto Germany Pte Ltd
7 Ubi Close, Alpine Centre
Singapore 408604

Sales Tel: 6922-3288 Fax: 6922-3289
Service Tel: 6922-3282 Fax: 6922-3283
Parts Tel: 6922-3285 Fax: 6922-3286

Opel Passenger and Commercial Vehicles

Email: enquiry@autogermany.sg
Web: opel.com.sg

30	1	FRT WHEELBEARING RH Dmgd		$ 657.00	✓
31	1	FRT LOW ARM RH Bent		$ 968.00	✓
32	1	FRT RIM RH cut		$ 937.00	✓

Parts Total: $ 17,965.50
Less10%: $ 1,796.55
Total : $ 16,168.95

Labour

Labour Description

No.			Price (SGD)	
1		To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts.	$ ~~3,250.00~~	1950
2		Carry out spray painting on affected area, FRT BUMPER, FRT RH FENDER, FRT SUPORT PANEL, FRT BONNET, FRT RH DOOR	$ ~~2,750.00~~	2200
3		To disconnect wire harness of electrical component to facilitate repairs,reconnect and check electrical function after repair	$ ~~220.00~~	180
4		To remove and replace RHF under carriage parts	$ 650.00	✓
5		To conduct 4 wheel alignment	$ ~~220.00~~	180
6		To conduct reset of ABS light on	$ 350.00	✓
7		To conduct transfer front door mechanism to new door panel	$ ~~650.00~~	325

Labour Total : $ 8,090.00

Others

Other Description

No.				Price (SGD)	
1		FRT TYRE RH Punctured		$ ~~350.00~~	280
2					

Other Total: $ 350.00

TOTAL: $ 24,608.95
GST (7%): $ 1,722.63

GRAND TOTAL : $ 26,331.58

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Adrian Ng
P/? 10/11/17

Excess $750.

Service Advisor

~~Cos~~ Authorised Repairs.

08 Pgs

SUPPLEMENTARY
VEHICLE NO: SFA6116J

QTY	PARTS DESCRIPTION	PRICE
1	Frt Absorber Connectors Arm RH Bent ✓	483 ✓
1	Air Intake insulator box cracked ✓	262 ✓

FINALIZE

AXA Insurance singapore Pte Ltd
Cecil Street #01-01 GB Building
Singapore 069542

GST Ref. No: 20-0000274-Z

Vehicle No: SFA6116J
Chasis No : W0LWT3D34EG008459
Engine No: B1131983B7GX0002
Date of accident :3/11/2017

Invoice No:

Invoice Date:

DESCRIPTION **AMOUNT SGD**

Parts

No.	Qty.	Description		Price (SGD)
1	1	FRT WINDSCREEN OUTER MLDG RH		$ 303.00
2	1	FRT QUARTER GLASS ASSY RH		$ 871.00
3	1	FRT BUMPER		$ 2,027.00
4	15	FRT BUMPER CLIP		$ 97.50
5	1	FRT BUMPER SIDE RETAINER RH		$ 150.00
6	1	FRT BUMPER BRACKET RH		$ 180.00
7	1	FRT BUMPER SPONGE		$ 324.00
8	1	FRT BUMPER PARKING SENSOR		$ 125.00
9	1	FRT BUMPER PARKING SENSOR SEAL		$ 12.00
10	1	FRT BUMPER PARKING SENSOR WIRE HARNESS		$ 487.00
11	1	RH HEADLAMP		$ 1,660.00
12	1	RH FOGLAMP		$ 293.00
13	1	RH FOG LAMP COVER		$ 185.00
14	10	FENDER INNERSHIELD CLIP		$ 65.00
15	1	FRT FENDER RH		$ 531.00
16	1	FRT FENDER INNERSHIELD		$ 207.00
17	1	FRT DOOR RH		$ 2,691.00
18	1	FRT SHOCK ABSORER RH		$ 311.00
19	1	FRT KNUCKLE ARM RH		$ 600.00
20	1	FRT WHEELBREARING RH		$ 657.00
21	1	FRT LOW ARM RH		$ 968.00
22	1	FRT RIM RH		$ 937.00

Supplementry

1	1	FRT ABSORBER CONNECTORS ARM Best		$ 483.00
2	1	AIR INTAKE RESONATOR BOX Ombeed.		$ 262.00

Total:	$	14,426.50
Less 10%:	$	1,442.65
Parts Total:	$	12,983.85

Labour

No.			Price (SGD)
1		TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	$ 1,950.00
2		CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA.FRT BUMPER , FRT RH FENDER FRT SUPPORT PANEL , FRT BONNET , FRT RH DOOR	$ 2,200.00
3		TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	$ 180.00
4		TO REMOVE AND REPLACE RHF UNDER CARRIAGE PARTS	$ 650.00
5		TO CONDUCT 4 WHEEL ALIGNMENT	$ 180.00
6		TO CONDUCT RESET OF ABS LIGHT ON	$ 350.00
7		TO CONDUCT TRANSFER FRONT DOOR MECHANISM TO NEW DOOR PANEL	$ 325.00

Labour Total : $ 5,835.00

Other

No.				Price (SGD)
1	1	FRT TYRE RH		$ 280.00

Other Total : $ 280.00

Total : $ 19,098.85
Excess: $ 750.00
GST (7%) : $ 1,284.42
Grand Total : $ 19,633.27

Yours Faithfully,

Kelvin Chew
Service Advisor
Tel: 68441985 Fax:68445185

Please check and finalize with me

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Saturday, 6 January, 2018 10:00 PM
To: SUR; assignments
Cc: kitty.teo@axa.com.sg
Subject: Survey report
Attachments: RE-INVOICE.PDF

This mail is associated with :
***SFA6116J (C0458832)**
OD
Nov 3 2017 3:00PM
[LIM SWEE HOE]
Auto Germany Pte Ltd

Hi

Please submit your survey report, workshop has submitted their bill.

Thanks.

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : Kitty Teo (AXA Insurance Pte Ltd)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Nov 2017		10 Nov 2017 11:43 Edit Adj Rpt	**S$19,098.85** Edit Estimates	**S$19,098.85** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**LIM SWEE HOE**, ID: S1675020D, Tel: +6597500065, Email: BDSA11@YAHOO.COM		
Vehicle Reg. No.:	**SFA6116J**	Date of Loss:	03/11/2017 15:00 - :59
Claim Type:	**OD** / C0458832	Policy/Cover Note No.:	P1994168 (Comprehensive)
		Excess:	S$750.00
Repairer:	**Auto Germany Pte Ltd (HQ)** 7 Ubi Close,, Apline Centre, 408604 Kaki Bukit - Tel: 6511 3025		
Handling Insurer:	**AXA Insurance Pte Ltd (Non-APW)** - Tel: ... [Handled by **Kitty Teo** - 6880 4602]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... [**Final Rpt** due 21/11/2017]		
Driver/Custodian:	LIM SWEE HOE (), NRIC: S1675020D, Tel: +6597500065		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

- AXA_SG (06/01/2018): **Survey report**

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFA6116J (C0458832)**
OD
Nov 3 2017 3:00PM
[LIM SWEE HOE]
Auto Germany Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View In Browser

Assessment Reports			1 per page		☑
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/11/17 14:54	Adjuster Immediate Advice	1	Load HTM	
2	30/11/17 09:54	Adjuster Immediate Advice	1	Load HTM	

Photos/Images			3 per page		☑
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/12/17 00:02	General View	1	Load JPG	☑
2	20/12/17 00:02	Chassis Number	1	Load JPG	☑
3	20/12/17 00:02	General View	1	Load JPG	☑
4	20/12/17 00:02	General View	1	Load JPG	☑
5	20/12/17 00:02	General View	1	Load JPG	☑
6	20/12/17 00:02	General View	1	Load JPG	☑
7	20/12/17 00:02	General View	1	Load JPG	☑
8	20/12/17 00:02	General View	1	Load JPG	☑
9	20/12/17 00:02	General View	1	Load JPG	☑
10	20/12/17 00:02	General View	1	Load JPG	☑
11	20/12/17 00:02	General View	1	Load JPG	☑
12	20/12/17 00:02	General View	1	Load JPG	☑
13	20/12/17 00:02	General View	1	Load JPG	☑
14	20/12/17 00:02	General View	1	Load JPG	☑
15	20/12/17 00:02	General View	1	Load JPG	☑
16	20/12/17 00:02	General View	1	Load JPG	☑
17	20/12/17 00:02	General View	1	Load JPG	☑
18	20/12/17 00:02	General View	1	Load JPG	☑
19	20/12/17 00:02	General View	1	Load JPG	☑
20	20/12/17 00:02	General View	1	Load JPG	☑
21	20/12/17 00:02	General View	1	Load JPG	☑
22	20/12/17 00:02	General View	1	Load JPG	☑
23	20/12/17 00:02	General View	1	Load JPG	☑
24	20/12/17 00:02	General View	1	Load JPG	☑
25	20/12/17 00:02	General View	1	Load JPG	☑
26	20/12/17 00:02	General View	1	Load JPG	☑
27	20/12/17 00:02	Reinspection Photo	1	Load JPG	☑
28	20/12/17 00:02	Reinspection Photo	1	Load JPG	☑
29	20/12/17 00:02	Reinspection Photo	1	Load JPG	☑
30	20/12/17 00:02	Reinspection Photo	1	Load JPG	☑
31	20/12/17 00:02	Reinspection Photo	1	Load JPG	☑
32	20/12/17 00:02	Reinspection Photo	1	Load JPG	☑

33	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
34	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
35	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
36	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
37	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
38	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
39	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
40	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
41	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
42	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
43	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
44	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
45	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
46	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
47	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
48	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
49	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
50	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
51	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
52	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
53	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
54	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
55	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
56	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
57	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑
58	20/12/17 00:02	**Reinspection Photo**	1	Load JPG	☑

Documentation			1 per page		☑
No	Finalized On	**AXA Insurance Pte Ltd (HQ)**		**Thumbnail**	**Print**
1	10/11/17 08:55	**EMAIL_ABS**	1	Load PDF	
2	10/11/17 08:55	**Estimate_ABS**	1	Load PDF	
3	10/11/17 08:55	**SFA6116J INSD GIA_ABS**	1	Load PDF	
4	10/11/17 08:55	**XD8304R TP NTUC GIA**	1	Load PDF	
No	**Relabel/Reorder**	**LKK Auto Consultants Pte Ltd (HQ)**		**Thumbnail**	**Print**
1	13/11/17 14:55	**REVISED ESTIMATE**	1	Load PDF	
2	30/11/17 09:50	**SUPPLEMENTARY LIST**	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way #27-01, AXA Tower
Singapore 068811

Our File No: CS/AXA17021555/AQBE2
Date: 12/01/2018

REFERENCE

Insured/Claimant:	LIM SWEE HOE	Policy No:	P1994168		
Date of Loss:	03/11/2017	Nature of Claim:	OD	Claim No:	C0458832

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SFA6116J**		
Make & Model:	OPEL CASADA, 1.6 (A)	Engine No:	B1131983B7GX0002
Reg. Date:	10/09/2014 (Man. Year: 2013)	Chassis No:	W0LWT3D34EG008459
Colour:	Black	Odometer:	28605 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S$115,000.00		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,189.45	13,263.85	3,925.60	22.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,090.00	5,835.00	2,255.00	27.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**25,279.45**	**19,098.85**	**6,180.60**	**24.45**
- Excess (S$)	750.00	750.00	0.00	0.00
(S$)	24,529.45	18,348.85	6,180.60	25.20
+ GST 7.00/7.00% (S$)	1,717.06	1,284.42	432.64	25.20
Nett Amount (S$)	**26,246.51**	**19,633.27**	**6,613.24**	**25.20**

INSPECTION

Date of Assignment:	10/11/2017		
Date Inspected:	10/11/2017	Inspected At:	Auto Germany Pte Ltd (HQ) 23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING **Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 12 Jan 2018)
Parts:	N/A	OPEL CASADA 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFA6116J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***FRT BONNET** (CONSISTENT)	Repair	1,843.00 FL	*- FL
2	1		***FRT WINDSCREEN OUTER MLDG RH** (CONSISTENT)	Deformed	303.00 FL	*303.00 FL
3	1		***FRT QUARTER GLASS ASSY RH** (CONSISTENT)	Cut	871.00 FL	*871.00 FL
4	1		***FRT BUMPER** (CONSISTENT)	Distorted	2,027.00 FL	*2,027.00 FL
5	1		***FRT BUMPER TOW COVER** (CONSISTENT)	Not Necessary	81.00 FL	*- FL
6	15		***FRT BUMPER CLIP** (CONSISTENT)	Necessary	97.50 FL	*97.50 FL
7	1		***FRT BUMPER SIDE RETAINER LH** (CONSISTENT)	Not Necessary	150.00 FL	*- FL
8	1		***FRT BUMPER SIDE RETAINER RH** (CONSISTENT)	Damaged	150.00 FL	*150.00 FL
9	1		***FRT BUMPER BRACKET LH** (CONSISTENT)	Not Necessary	180.00 FL	*- FL
10	1		***FRT BUMPER BRACKET RH** (CONSISTENT)	Damaged	180.00 FL	*180.00 FL
11	1		***FRT BUMPER BRACKET TOP CENTRE** (CONSISTENT)	Not Necessary	267.00 FL	*- FL
12	1		***FRT BUMPER SPONGE** (CONSISTENT)	Cracked	324.00 FL	*324.00 FL
13	1		***FRT BUMPER PARKING SENSOR** (CONSISTENT)	Damaged - 1 pc only	350.00 FL	*125.00 FL
14	1		***FRT BUMPER PARKING SENSOR SEAL** (CONSISTENT)	Damaged - 1 pc only	24.00 FL	*12.00 FL
15	1		***FRT BUMPER PARKING SENSOR WIRE HARNESS** (CONSISTENT)	Cracked	487.00 FL	*487.00 FL
16	1		***FRT GRILLE** (CONSISTENT)	Not Necessary	870.00 FL	*- FL
17	1		***FRT GRILLE LOGO** (CONSISTENT)	Not Necessary	98.00 FL	*- FL
18	1		***RH HEADLAMP** (CONSISTENT)	Smashed	1,660.00 FL	*1,660.00 FL
19	1		***RH FOG LAMP** (CONSISTENT)	Cracked	293.00 FL	*293.00 FL
20	1		***RH FOG LAMP COVER** (CONSISTENT)	Missing	185.00 FL	*185.00 FL
21	10		***FENDER INNERSHIELD CLIP** (CONSISTENT)	Necessary	65.00 FL	*65.00 FL
22	1		***FRT FENDER RH** (CONSISTENT)	Distorted	531.00 FL	*531.00 FL
23	1		***FRT FENDER SIGNAL LAMP RH** (CONSISTENT)	Not Necessary	188.00 FL	*- FL
24	1			Deformed	207.00 FL	*207.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			***FRT FENDER INNERSHIELD RH** (CONSISTENT)			
25	1		***FRT DOOR RH** (CONSISTENT)	Distorted	2,691.00 FL	*2,691.00 FL
26	1		***FRT DOOR HINGE UPP RH** (CONSISTENT)	Not Necessary	185.00 FL	*- FL
27	1		***FRT DOOR HINGE LOW RH** (CONSISTENT)	Not Necessary	185.00 FL	*- FL
28	1		***FRT SHOCK ABSORBER RH** (CONSISTENT)	Bent	311.00 FL	*311.00 FL
29	1		***FRT KNUCKLE ARM RH** (CONSISTENT)	Bent	600.00 FL	*600.00 FL
30	1		***FRT WHEELBEARING RH** (CONSISTENT)	Necessary	657.00 FL	*657.00 FL
31	1		***FRT LOW ARM RH** (CONSISTENT)	Bent	968.00 FL	*968.00 FL
32	1		***FRT RIM RH** (CONSISTENT)	Cut	937.00 FL	*937.00 FL
33	1		***FRT TYRE RH** (CONSISTENT)	Punctured	350.00 FS	*280.00 FS
34	1		***FRT ABSORBER CONNECTORS ARM RH** (CONSISTENT)	Bent	483.00 FL	*483.00 FL
35	1		***AIR INTAKE INSULATOR BOX** (CONSISTENT)	Cracked	262.00 FL	*262.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**19,060.50**	**14,706.50**
- List Item Discount on L Items 10.00/10.00% (S$)	1,871.05	1,442.65
Total Parts (S$)	**17,189.45**	**13,263.85**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	3,250.00	1,950.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT RH FENDER, FRT SUPPORT PANEL, FRT BONNET, FRT RH DOOR	New	2,750.00	2,200.00
3	TO REMOVE AND REPLACE RHF UNDER CARRIAGE PARTS	New	650.00	650.00
4	TO CONDUCT 4 WHEEL ALIGNMENT	New	220.00	180.00
5	TO CONDUCT RESET OF ABS LIGHT ON	New	350.00	350.00
6	TO CONDUCT TRANSFER FRONT DOOR MECHANISM TO NEW DOOR PANEL	New	650.00	325.00
7	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	220.00	180.00
		Gross Labour Cost (S$)	**8,090.00**	**5,835.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >