COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

ALG
LKK
CLS
Jumani

VEHICLE NO : SHA 2487R **DATE 17/11/2017 11:41**

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover Xrepair			$ 538.80	
	Front Bumper Sponge ?			$ 136.30	
	Front Bumper Reinforcement ?			$ 504.10	
	Front Bumper Bracket Top (RH) ?			$ 22.40	
	Front Bumper Protector (RH) Xrepair			$ 29.20	
	Front Bumper Bracket (RH) ?			$ 20.10	
	Front Bumper Side Bracket ?			$ 14.30	
	SUB TOTAL			**$ 1,265.20**	
	LESS 20%			$ 253.04	
	DISCOUNTED TOTAL			**$ 1,012.16**	
	Front Number Plate X			$ 25.00	**Nett**
	Front No Plate Trim Cover X			$ 30.00	**Nett**
				$ 55.00	
	Labour Charge				
	Panel Beating			$ ~~350.00~~ 100	
	Spray Painting Charge			$ ~~200.00~~ 180	
	TOTAL LABOUR			**$ 550.00**	
	ESTIMATE TOTAL			**$ 1,617.16**	

Kalai CCCC
17/11/17 1445hrs
2 Days
4s
After Repair photo

LKK A
the P
• To
• To
• Parts
• The
• No
• Supplem
is subject
notify
ng:
nting
resurvey
ation
s on a "Without Prejudice" basis
ation(s) is allowed
must be resurveyed a
approval from Insurance Co
Acknowledged by repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.