Surveyor: Tanjhin REF: ATG

ASSIGNMENT

From: Date: 22.11.2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJQ 2459P

at Workshop m/s: Charn's Customcraft

of: Blk 1010 Bukit Batok Lane 3 #01-105

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 1pm - 3pm

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJQ 2459P Yr Regn: 2009 April.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Subaru Forester. D.O: 1994

Colour: Silver A.C: Insured / Std / NI / NA

Sp.Reading: 157488 T.Radio: Insured / Std / NI / NA

Eng/No:

C/No: JF1SH5K569G018871

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65R15

R: 〃 〃

BS / DUN / EXHOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YORO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	22/11/17 @ 2-30 pm

Survey held at: Charn's custom craft

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R/F O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time File Pass to?

1:

Date/Time File Return to?

2:

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp $ ☐ Interview $ ☐ Tech Inve $ ☐ Weekend $

Report Format :

Lump Sum / I.B.I: $

Survey Fee:

Transportation:

Photos:

Other:

TOTAL: