pegasus
PEGASUS ENGINEERING & TRADING

LKK Auto Consultants hence notify the Repairer of the following:
- No resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Repair survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and re-submitted for approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Agreed
LKK
1/5 $2800
3 day.
21/11/17
Zhu zhu. Albert Ngan

Third Party Insurer : AIG
Insured's Veh No : SKP6002R
Date of accident : 12.11.2017

Messrs Grab Rentals Pte Ltd

Date : 13.11.2017

21.11.2017 @ 0940 hrs
LKK Marcus

Estimate To Repair Honda Vezel 1.5 Hybrid X (A)
Vehicle No : SLM1776C
Chassis No : RU31228893

S/No	Quantity		Description		Unit price	Amount
			LIST ITEMS			
1	1	pc	radiator grille	CM	$ 285.00	$ 285.00
2	1	pc	radiator grille outer garnish	〃	$ 385.00	$ 385.00
3	1	pc	radiator grille emblem badge	〃	$ 23.40	$ 23.40
4	1	pc	radiator grille moulding	〃	$ 75.00	$ 75.00
5	6	ps	radiator grille clips	〃	$ 3.90	$ 23.40
6	1	pc	front bumper 821.70	DD/Ton	$ 927.50	$ 927.50
7	1	pc	front bumper reinforcement	DD	$ 321.00	$ 321.00
8	1	pc	front bumper lower centre air grille	〃	$ 180.00	$ 180.00
9	6	ps	front bumper clips	〃	$ 3.90	$ 23.40
10	1	pc	front bumper lower	〃	$ 381.00	$ 381.00
11	2	ps	front bumper side retainers	〃	$ 23.00	$ 46.00
12	10	ps	front bumper clips	〃	$ 3.90	$ 39.00
13	1	pc	radiator grille upper centre bracket	〃	$ 52.80	$ 52.80
14	2	ps	radiator grille upper side brackets	〃	$ 25.20	$ 50.40
15	2	ps	headlamps 1759.40	1pc o/s one	$ 1,859.40	$ 3,718.80
16	2	ps	headlamp lower brackets	1pc o/s one	$ 35.00	$ 70.00
17	2	ps	front bumper spot lights	〃	$ 327.70	$ 655.40
18	2	ps	front bumper spot lights garnish	〃	$ 45.20	$ 90.40
						$ 7,347.50
			Less 20% 3377.3 2701.84			$ 1,469.50
						$ 5,878.00
			SPECIAL NETT ITEMS			40
19	1	pc	front licence plate	one	$ 80.00	$ 80.00
						$ 80.00
			LABOUR & MISC. CHARGES			
1			To check electrical lighting concerned.		20	$ 60.00
2			To rust-proofing of the affected areas.		11	$ 80.00
3			Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.		350	$ 600.00
4			Putty and spray painting of the affected portion.		400	$ 650.00
			3511.80			$ 1,390.00
			Grand Total			$ 7,348.00

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o **51 Defu Lane 10 Singapore 539216**