Surveyor Rame REF: 22736/14P 7253A

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 9991Y

at Workshop m/s PERFORMANCE

of 305, ALEXANDRA RD

Insured: LCR/TP

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) Unlimited

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / RES / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLC 9991Y Yr Regn: 2016 APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: B.M.W 116D 5DR c.c 1496

Colour WHITE A/C Insured / Std / NI / NA

Sp.Reading 40169 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA1V720 80V724322

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	26/11/17	D.O.I.	05/12/17

Survey held at PERFORMANCE

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time. File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($ ☐ : Interview ($ ☐ : Tech. Inve ($ ☐ : Weekend ($

Report Format :

Lump Sum / I.B.I: ($

Survey Fee

Transportation

Photos

Others