Daywatch Neil. REF: EQI

ASSIGNMENT

From: Date: 30/11/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 3249P

at Workshop m/s: Kah Motor

of: 15 UBI Road 4 , 408610

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Mr. Lim

11 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLN3249P Yr Regn: 28 Apr 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Jazz c.c: 1318

Colour: purple A/C: Insured / Std / NI / NA

Sp.Reading: 18251 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMGK3850HX200455

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD Rim or

Tyre Size F: 175/65 R 15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	8 mm	L/Bal.	8 mm

D.O.A.: D.O.I. 30-11-17

Survey held at: w/s 11AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time File Pass to?

1

Date/Time File Return to?

2

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp $ ☐ Interview $ ☐ Tech Info $ ☐ Weekend $

Survey Fee

Transportation

Photos

Other

TOTAL

Report Format :

Lump Sum / I.B.I: $