企业壹号

# ENTERPRISE ONE AUTO PTE. LTD.

8 Kim Chuan Terrace, Singapore 537031
T: +65 6748 3149,7115 | F: +65 6741 8132 | E: premierone@hotmail.com
UEN: 200612423G

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- Display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date: 28/11/2017

To: AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

SGU7644C

**Estimate Cost Of Repair For HONDA AIRWAVE (SLC ~~9865~~ D)**

To supply the following parts:

| | | | Amount | |
|---|---|---|---|---|
| 1 | Rear Bonnet | Buc | $ 1,382.50 | 986.2 |
| 2 | Rear Bumper | RC | $ 1,078.50 | 980.2 |
| 3 | Rear Bumber Lower Lip | OA | $ 850.00 | 350 (SN) |
| 4 | Rear Bonnet Hinge (2PCS) | X | $ 159.00 | |
| 5 | Reverse Sensor | X | $ 250.00 | |
| 6 | Reverse Camera | X | $ 280.00 | |
| | | | **Sub Total** $ 4,000.00 | 1966.4 |
| | | | Less 20% $ 800.00 | |
| | | | **Total on Parts** $ 3,200.00 | 1573.12 |

NN

Labour Charges:

| | | | |
|---|---|---|---|
| 1 | To panel beat / reinstate damaged parts | $ 800.00 | ~~300~~ 400 |
| 2 | To spray paint replaced parts | $ 800.00 | 500 |
| 3 | To replace damaged accessories | $ 300.00 | 50 |
| | | **Total on Labour** $ 1,900.00 | 950 |
| | | **Total Repair Cost** **$ 5,100.00** | |

2873.12

20%: 2300

Prepare By

Sunny Jiang

3Days.
Lump sum repair.
After repair photos.
Guo Qiang - 8880282
01/12/17