Surveyor: Tanfulin | REF: ALG

ASSIGNMENT

From: | Date: 13.12.2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL 1409E

at Workshop m/s: Accord Auto

of: Blk 1009 Bukit Batok Lane 3 #01-80

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

before 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SKL1409E | Yr Regn: 2013 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Golf | c.c: 1395

Colour: Black | A/C: Insured / Std / NI / NA

Sp Reading: 80411 | T Radio: Insured / Std / NI / NA

Eng/No: 1

C/No: WWZZZ1KZDW160660

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 KU

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A.: | D.O.I.: 13/12/17 11:50

Survey held at: Accord Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time. File Pass to?

1)

Date/Time. File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp $ | ☐ : Interview $ | ☐ : Tech Invs $ | ☐ : Weekend $

Survey Fee:

Transportation: ___S + R$ ___S

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)