Surveyor: XBCL. | REF: AXA

ASSIGNMENT

From: | Date: 13/12/17

Estimated Cost:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKH 8958L

at Workshop m/s: Ethicarz

of: 56 Tayeng way, Tayeng Enterprise Building #04-04, 508775

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: John

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S | O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SKH8958L | Yr Regn: 25 Jan 2013

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Renault Scenic III | c.c 1461

Colour: Brown | A/C: Insured / Std / NI / NA

Sp.Reading: 100402 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF1JZ09B34 840,407

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (In order) / Jammed / Leaked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / (STD A/Rim) or

Tyre Size: F: 215/55R17

R: "

BS / (DUN) / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front			Rear		
R/Bal.	6	mm	R/Bal.	6	mm
L/Bal.	6	mm	L/Bal.	6	mm
D.O.A.			D.O.I.	13-12-17	

Survey held at: W/S 3:30pm

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? 1) | [ ] : Preli. Report | [ ] : Final Report

Date/Time, File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: [ ] Site Insp. ($) __S - RS __SI

[ ] Interview ($) Photos

[ ] Tech. Invs ($) Others

[ ] Weekend ($)

TOTAL

Report Format:

Lump Sum / I.B.I: ($)