Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728
Fax : 64816131

Not Authorised
U/Sup &
Renew After Paint

India International Insurance Pte Ltd
64 Cecil Street #04/05-00
IOB Building
Singapore 049711

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vehicle No : SLP 2775 H
Make : Toyota Altis
Year : 2009

Qty	Description		Unit Price		Amount	
Estimate Cost Of Repair						
1 pc	Rear boot lid	repair		R	$753.10	
1 pc	Rear boot lid emblem " Logo "	nil			$45.10	
1 pc	Rear boot lid emblem " 1.6 "	nil			$22.90	
1 pc	Rear boot lid emblem " Corolla "	nil			$46.30	
1 pc	Rear boot lid emblem " Altis "	nil			$40.10	
1 pc	Rear boot lid emblem " LX "	nil			$25.20	
1 pc	Rear boot lid inner lock	bent			$115.60	
2 pcs	Rear boot lid reflector	?	$255.10		$510.20	
1 pc	Rear bumper	deform			$485.20	
2 pcs	Rear bumper side retainer	crack	$55.10		$110.20	
1 pc	Rear bumper beam/sponge	crack			$255.10	
2 pcs	Rear bumper bracket	n/c bent	$105.20	NSDII	$210.40	4105.20
1 pc	Rear boot rubber	deform			$145.70	508.20
1 pc	Rear end panel	? dent			$525.70	?
1 pc	Rear end panel inner garnish	? crack			$185.60	
					$3,476.40	2107.90
			Less 25 %		$869.10	526.97
					$2,607.30	1580.93
S Nett						
10 pcs	Rear bumper clip		$2.50		$25.00	
1 pc	Rear reverse sensor				$200.00	?
					$225.00	
Labour Charges						600
	Remove/renew the above parts including knocking, welding etc.				$1,200.00	~~600~~
	To putty & spray paint front & rear accident affected portion.				$1,000.00	600
				balance c/f	$5,032.30	

SLP 2775 H

	balance b/f	$5,032.30
Labour Charges		
To check and reconnect wiring.		$40.00 20
To spray anti rust on accident affected portion.		$100.00 ~~100~~ 30
Remove/refit rear boot upholstery/cushion seat/floor carpet to facilitate repair.		$120.00 60
	Total	$5,292.30

Jump Sum – $ 2,650.00 – 4 days