ASS. REC. BY: REF: CS/LPC17024216/R1fd3e2

Surveyor: Rasul / Mermen

ASSIGNMENT (Office)

From (Person): Gerald Poh of: LPC Date/Time: 21/12/17 @ 8.25am

Estimated Cost: Bill to:

OI / TP / WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJN4651C Insured:

at Workshop m/s: Woon Meng Motor Tel: 6316 1131

of: 50 Bukit Batok Street 23 #01-06

Policy No: Z17VP05013207 Claim No: 17/17117/VP05/020273

Sum Insured: Excess: —

Make of Veh: (Client's Record) D.O.A. 12/12/2017

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 10.51am @ Person Contacted: Mrs. Heng Vehicle: IN / OUT

Date/Time	Action/Instruction (✓ Estimate
	SJN4651C - CC4/LPC17023759/Uua3 D.O.A: 12/12/17
22/12	revert via mermen
22/12 @	12:56pm inform by Chew Beng Kee authorise repair
22/12 @	2.45pm inform Ms Heng authorise repair excess $0.

GIA / PR Seen: Consistent / Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

D.O.A. 12/12/17 D.O.I. 21/12/17

Survey held at Woon Meng

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Part by Part $8570.05+ (Red: 2546.10 '220%)

RECEIVED 2 0 APR 2018

Date/Time, File Pass to? 1) 26/4 Typist ☐: Preli. Report ☑: Final Report

Date/Time, File Return to? 2)

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐: Site Insp ($) S + RS SI ☐: Interview ($) ☐: Tech. Invs ($) ☐: Weekend ($)

Report Format: OD

Lump Sum / I.S: ($ 8570.05)

170+15=185

185 x 20% = 37

Survey Fee:	185+37
Transportation:	50
Photos	50
Others	113
TOTAL	435+10

OSP 3/5/18

(445)