	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	SET BUMPER LOWER REAR RIVET	Reviewing		0	NOT NECESSARY	
		0	SET BUMPER LOWER REAR CLIP	Reviewing		66	NECESSARY	
		0	EXHAUST MOUNTING REAR	Reviewing		0	NOT NECESSARY	
		0	SET BOOT FINISHER CLIP	Reviewing		0	NOT NECESSARY	
		0	BOOT STICKER "TRANS-CAB"	Reviewing		30	NECESSARY	
		0	BOOT STICKER "6555-3333"	Reviewing		30	NECESSARY	
		0	SET FENDER WHEELARCH REAR RH CLIP	Reviewing		0	NOT NECESSARY	
		0	SET FENDER WHEELARCH REAR LH CLIP	Reviewing		0	NOT NECESSARY	
		0	TAILLAMP CLIP RH	Reviewing		0	NOT NECESSARY	
		0	TAILLAMP CLIP LH	Reviewing		0	NOT NECESSARY	
		0	REAR WINDSCREEN SEALANT	Reviewing		0	NOT NECESSARY	

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
		0		PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	0	400	0	0	Reviewing		
		0		TO RUST-PROOFING OF THE AFFECTED AREAS.	0	30	0	0	Reviewing		
		0		TO REINSTALL REAR BUMPER PARKING SENSOR.	0	60	0	0	Reviewing		
		0		TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	0	60	0	0	Reviewing		
		0		TO REPAIR AND REALIGN REAR EXHAUST PIPE.	0	0	0	0	Reviewing		
		0		TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	0	0	0	0	Reviewing		
		0		TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	0	Reviewing		
		0		TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	0	Reviewing		
		0		TOWING FEES.	0	0	0	0	Reviewing		
		0		TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	0	0	0	0	Reviewing		

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		BUMPER BEAM REAR	Bent	0	777.52	No		10			699.77	Reviewing	
		0	1		BUMPER BEAM BRACKET LH REAR	Repair	0	0	No		10			0	Reviewing	
		0	1		BUMPER BEAM BRACKET RH REAR	Repair	0	0	No		10			0	Reviewing	
		0	1		BOOT REAR	Bent	0	2872.68	No		10			2585.41	Reviewing	
		0	1		BOOT FINISHER	Serviceable	0	0	No		10			0	Reviewing	
		0	1		BOOT WEATHERSTRIP	Serviceable	0	0	No		10			0	Reviewing	
		0	1		BOOT REFLECTOR LAMP LH	Serviceable	0	0	No		10			0	Reviewing	
		0	1		BOOT REFLECTOR LAMP RH	Serviceable	0	0	No		10			0	Reviewing	
		0	1		BOOT BADGE 'RENAULT'	Necessary	0	225.36	No		10			202.82	Reviewing	
		0	1		BOOT BADGE	Necessary	0	225.36	No		10			202.82	Reviewing	
		0	1		BOOT SWITCH	Serviceable	0	0	No		10			0	Reviewing	
		0	1		BOOT LOCK	Repair	0	0	No		10			0	Reviewing	
		0	1		BOOT LOCK CATCH	Repair	0	0	No		10			0	Reviewing	
		0	2		LICENCE PLATE LAMP	Serviceable	0	0	No		10			0	Reviewing	
		0	2		BOOT RUBBER PLUG	Serviceable	0	0	No		10			0	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Sum Insured		0
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Type		
License Issue Date		mm/dd/yyyy
License Expiration Date		mm/dd/yyyy
Address	BLK 40 BEO CRESCENT, 160040, Singapore	
Address type	Personal Correspondence	
Gender	Male	
Marital status	Unknown	
Identification #	S7130363B	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	ADJUSTED AMOUNT	STATUS	SHARE	CLONE
KHOR Saw Theng	1/2/18 10:37 AM	0	6926.49	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKK INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	October 17, 2018
Immediate Advice and Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 4, 2018
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 24, 2018
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 24, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	May 24, 2018
GA128744-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	KHOR Saw Theng	January 2, 2018
GA128744-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	KHOR Saw Theng	January 2, 2018
Preliminary Advice.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	January 2, 2018
email received from workshop with TP GIA & Estimate.msg	Letters and Correspondence	Others	PATIL Amol	December 29, 2017
SKW3687Y INSD GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Amol	December 29, 2017
SHF687S TP GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Amol	December 29, 2017