Singapore | REF: ATG | 9819C

ASSIGNMENT

From: Date: 03012018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 1830Y

at Workshop m/s Ethicarz

of Loyang

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No SKZ1830Y Yr Regn: 13 Jan 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Vezel c.c 1496

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 35355 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU1110 8227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	29/12/2	D.O.I.	3/1/18

Survey held at Ethicarz

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Front.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time. File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I. $

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp $

☐ : Interview $

☐ : Tech. Insp $

☐ : Weekend $

Survey Fee:

Transportation: $ + RS $

Photos

Others

TOTAL