Surveyor: Rasul | REF: ~~AH~~ 2LG | 52295

ASSIGNMENT

From: | Date: 05.01.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKK 6777P

at Workshop m/s Volkswagen

of 247 Alexandra Rd

Insured:

Policy No.

Claims No

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 10.30am Owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKK 6777P Yr Regn: 2017 JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLKSWAGEN TIGUAN HL c.c 1395

Colour: BROWN A/C: Insured / Std / NI / NA

Sp.Reading: A546 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVGZZZSN2HW371778

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R18

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or CONTINENTAL

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 03/01/18 D.O.I. 05/01/18

Survey held at VOLKSWAGEN

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time File Pass to?

1)

Date/Time File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. $ ☐ Interview $ ☐ Tech. Insp. $ ☐ Weekend $

Report Format :

Lump Sum / I.B.I: $

Survey Fee:

Transportation: ___$ + ___$

Photos

Others

TOTAL