REF: ECICS

ASSIGNMENT

From: Date: 15/01/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKJ 9680 U

at Workshop m/s: Lim Tan Motor

of: Blk 176, Sin Ming Drive #03-09/10

Insured:

Policy No.

Claims No.

Sum Insured: Excess: $750.00

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 88 64%

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1-B, / % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date: Person Contacted:

Veh No: SKJ 9680U Regn: 05 13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mazda A3 cc: 1598

Colour: M. Grey A/C: Insured / Std / Nil / NA

Sp. Reading: 65166 T/Radio: Insured / Std / Nil / NA

Eng No:

C No: JM 6BL10Z200360984

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S'Rim / STD A/Rim or

Tyre Size F: 215/45ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front			Rear		
R.Bal.	7	mm	R.Bal.	7	mm
L.Bal.	7	mm	L.Bal.	7	mm
D.O.A.	12/1/18		D.O.I.	15/1/18	

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

16/1 File pass to [illegible]

2/2/2018

Date/Time File Pass to: 5/2 Typist

Date/Time File Return to:

☐ Preli. Report

☑ Final Report

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee: ☐ Site Insp $ / Interview $ / Tel $ / [illegible] $

Survey Fee / Transportation / Photo / [illegible]

Report Format: OD

Lump Sum: LB $ 3768.40

Total: 250