| | EDIT | SR NO | NAME | ACTION | AMOUNT | COMMENT | REMOVE |
|---|---|---|---|---|---|---|---|
| ☐ | ✎ | 5 | FRONT NUMBER PLATE | Reviewing | 30 | BENT | 🗑 |

| | EDIT | SR NO | QUANTITY | MATERIAL | SIDE | PART NAME | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPR./BTTR% | DISCOUNT% | SALVAGE% | PART PRICE(NET) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 11 | 4 | | | REAR BUMPER CLIP | | | Necessary | 3.9 | | 20 | | 12.48 |
| | | 12 | 2 | | | REAR BUMPER SIDE RETAINER | | | Necessary | 17.1 | | 20 | | 27.36 |
| | | 13 | 1 | | | REAR END PANEL | | | Bent | 347 | | 20 | | 277.6 |
| | | 14 | 1 | | | REAR END PANEL GARNISH | | | Deformed | 61.8 | | 20 | | 49.44 |
| | | 15 | 1 | | | REAR FENDER INNER TRIM LH | | | Deformed | 182.7 | | 20 | | 146.16 |
| | | 16 | 1 | | | SPARE TYRE WELL | | | Buckled | 948.5 | | 20 | | 758.8 |
| | | 17 | 1 | | | SPARE TYRE WELL LOWER PANEL | | | Repair | 0 | | 20 | | 0 |
| | | 18 | 1 | | | SPARE TYRE WELL INSULATOR | | | Necessary | 74.1 | | 20 | | 59.28 |
| | | 19 | 1 | | | SPARE TYRE TOP COVER | | | Deformed | 340.7 | | 20 | | 272.56 |
| | | 20 | 1 | | | FRONT BUMPER | | | Deformed | 638 | | 20 | | 510.4 |
| | | 21 | 1 | | | FRONT BUMPER SIDE RETAINER LH & RH (N/S) | | | Cracked | 19.8 | | 20 | | 15.84 |
| | | 22 | 10 | | | FRONT BUMPER CLIP | | | Necessary | 3.9 | | 20 | | 31.2 |

Labour

| EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT |
|---|---|---|---|---|---|---|---|---|

## Detailed Assessment

Inspection Date *

01/12/2018

Total Loss

**Yes** **No**

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

## Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes **No**

Footbrake (Serviceable)

Yes **No**

Handbrake (Serviceable)

Yes **No**

Engine Modification

**Yes** No

Pre-accident condition

Good

## Tyre Condition

Age of Tyres

Front Tyre Size

205/55R16

Spare wheel

Rear Tyre Size

205/55R16

| | |
|---|---|
| FNOL INFORMATI... | APT BLK 514 JELAPANG ROAD, 670514, Singapore |
| POST SURVEY INF... | |

| | |
|---|---|
| CATEGORY | Address type |
| FNOL INFORMATI... | Personal Correspondence |
| POST SURVEY INF... | |

| | |
|---|---|
| CATEGORY | Gender |
| FNOL INFORMATI... | Male |
| POST SURVEY INF... | |

| | |
|---|---|
| CATEGORY | Marital status |
| FNOL INFORMATI... | Unknown |
| POST SURVEY INF... | |

| | |
|---|---|
| CATEGORY | Identification # |
| FNOL INFORMATI... | S1675927I |

POLICY INFORMAT... TPVD HONDA

ASSESSMENT INFO... HONDA

CATEGORY Model

POLICY INFORMAT... CIVIC-1.8 L (A)

ASSESSMENT INFO... CIVIC 1.8L A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... JHMFD163075205902

CATEGORY Date of Birth

FNOL INFORMATI... July 5, 1964

POST SURVEY INF... mm/dd/yyyy

CATEGORY Age

FNOL INFORMATI... 53

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

Direct settlement

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents Assessment Metrics Notes Add

| CREATED USER | VERSION DATE | ESTIMATED AMOUNT | APPROVED AMOUNT | STATUS | SHARE | CLONE |
|---|---|---|---|---|---|---|
| User Portal | 5/30/18 10:31 AM | 5700 | 5700 | Open | Share | Clone |
| NG Stacey | 1/12/18 11:18 AM | 7183.36 | 7183.36 | Open | Share | Clone |

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|---|---|---|---|---|
| Preliminary Advice.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | January 15, 2018 |
| GIA REPORT OF SJV3891R (TP).PDF | Reports & Statement | GIA Report | KADRI Mateen | January 12, 2018 |
| GIA REPORT OF SJS1825L (INSD).PDF | Reports & Statement | GIA Report | KADRI Mateen | January 12, 2018 |
| EMAIL.msg | Letters and Correspondence | Workshop | KADRI Mateen | January 12, 2018 |

Direct settlement

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents Assessment Metrics Notes

Document Type Document SubType

Upload Documents

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|---|---|---|---|---|
| GIA SEARCH.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | June 19, 2018 |
| RENTAL RECEIPT.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | June 19, 2018 |
| WORKSHOP INVOICE.pdf | Invoice | Repairer | LKK AUTO CONSULTANTS PTE LTD (TP) | June 19, 2018 |
| DISCHARGE VOUCHER.pdf | Forms / Claim Documents | Satisfaction / Discharge Voucher | LKK AUTO CONSULTANTS PTE LTD (TP) | June 19, 2018 |