CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 384G

MAKE :

MODEL : HYUNDAI SONATA

AigAsia -4S

TS

DATE 12/1/2018

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			$ 578.40
	Rear Bumper Reinforcement			$ 483.30
	Rear Bumper Clip			$ 22.00
	Rear Bumper Sponge ?			$ 137.40
	Rear Bumper Under Cover ?			$ 185.80
	Rear Bumper Protector (LH/RH) x repair		$ 38.00	$ 76.00
	Rear Panel x repair			$ 391.80
	Rear Panel Garnish x			$ 95.80
	SUB TOTAL			**$ 1,970.50**
	LESS 20%			$ 394.10
	DISCOUNTED TOTAL			**$ 1,576.40**
	Rear Bumper Reverse Sensor			$ 135.70 **Nett**
	Rear Bumper Advertisement Logo			$ 50.00 **Nett**
	Rear Bumper Rubber Mat			$ 50.00 **Nett**
	Rear Fender Advertisement Logo (LH/RH)		$ 100.00	$ 200.00 **Nett**
				$ 435.70
	Labour Charge			
	Panel Beating			$ ~~350.00~~ 200
	Spray Painting Charge			$ ~~200.00~~ 180
	Wiring Charge			$ ~~50.00~~ x
	Remove/Refix Reverse Sensor			$ ~~120.00~~ 20
	TOTAL LABOUR			**$ 720.00**
	ESTIMATE TOTAL			**$ 2,732.10**

Kalvin LKK

12/1/18 10.10 hrs.

2 Days

4S

After Repair pho

LKK Auto Con... the R... ...ce notify
- To res... ...g:
- To di... ...ay ca... ...ing
- Parts prices a... ...ubject to confirmatio... ...rvey
- Third party s... ...Sign a Waiver Prej... ...e" basis
- No liegc...
- Supp... ...and
is subje... ...insurance and ...from insurance company

Acknowledge... ...er

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.