	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		10	SET BUMPER LOWER REAR CLIP	Reviewing	66	NECESSARY	
		11	EXHAUST MOUNTING REAR	Reviewing	0	SERVICEABLE	
		12	SET BOOT FINISHER CLIP	Reviewing	0	NOT NECESSARY	
		13	BOOT STICKER "TRANS-CAB"	Reviewing	0	NOT NECESSARY	
		14	BOOT STICKER "6555-3333"	Reviewing	0	NOT NECESSARY	
		15	BOOT INNER TRIM CLIP	Reviewing	0	NOT NECESSARY	
		16	SET FENDER WHEELARCH REAR RH CLIP	Reviewing	0	NOT NECESSARY	
		17	SET FENDER WHEELARCH REAR LH CLIP	Reviewing	0	NOT NECESSARY	
		18	FENDER INNER TRIM CLIP LH	Reviewing	0	NOT NECESSARY	
		19	FENDER INNER TRIM CLIP LH	Reviewing	0	NOT NECESSARY	
		20	TAILLAMP CLIP RH	Reviewing	0	NOT NECESSARY	
		21	TAILLAMP CLIP LH	Reviewing	0	NOT NECESSARY	
		22	REAR WINDSCREEN SEALANT	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	45	1			EXHAUST CAP REAR			Repair	0		10		0	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	220	0	0	Reviewing		
	2		PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	200	0	0	Reviewing		
	3		TO RUST-PROOFING OF THE AFFECTED AREAS.	0	0	0	Reviewing		
	4		TO REINSTALL REAR BUMPER PARKING SENSOR.	60	0	0	Reviewing		
	5		TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing		
	6		TO REPAIR AND REALIGN REAR EXHAUST PIPE.	0	0	0	Reviewing		
	7		TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	0	0	0	Reviewing		
	8		TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing		
	9		TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing		
	10		TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	0	0	0	Reviewing		
	11		TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing		
	12		TOWING FEES.	0	0	0	Reviewing		

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		12	1			BUMPER BEAM BRACKET RH REAR			Repair	0		10		0	Reviewing	
		13	1			BOOT REAR			Repair	0		10		0	Reviewing	
		14	1			BOOT FINISHER			Serviceable	0		10		0	Reviewing	
		15	1			BOOT WEATHERSTRIP			Serviceable	0		10		0	Reviewing	
		16	1			BOOT REFLECTOR LAMP LH			Serviceable	0		10		0	Reviewing	
		17	1			BOOT REFLECTOR LAMP RH			Serviceable	0		10		0	Reviewing	
		18	1			BOOT BADGE 'RENAULT'			Serviceable	0		10		0	Reviewing	
		19	1			BOOT BADGE			Serviceable	0		10		0	Reviewing	
		20	1			BOOT STRUT LH			Serviceable	0		10		0	Reviewing	
		21	1			BOOT STRUT RH			Serviceable	0		10		0	Reviewing	
		22	1			BOOT HINGE LH			Repair	0		10		0	Reviewing	
		23	1			BOOT HINGE RH			Repair	0		10		0	Reviewing	
		24	1			BOOT INNER TRIM			Serviceable	0		10		0	Reviewing	
		25	1			BOOT SWITCH			Serviceable	0		10		0	Reviewing	
		26	1			BOOT LOCK			Repair	0		10		0	Reviewing	
		27	1			BOOT LOCK CATCH			Repair	0		10		0	Reviewing	
		28	2			LICENCE PLATE LAMP			Serviceable	0		10		0	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Sum Insured		0
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Type		
License Issue Date		mm/dd/yyyy
License Expiration Date		mm/dd/yyyy
Address		
Address type		
Gender	Unknown	
Marital status	Unknown	
Identification #	S1204493C	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
NG Stacey	1/23/18 3:45 PM	3237.7	3237.7	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Immediate Advice (with mandate) dd 110818.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 11, 2018
RENTAL RATE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 11, 2018
LTA.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 11, 2018
Letter to OI_.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	August 11, 2018
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 11, 2018
Preliminary Advice.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	January 26, 2018
NEW EMAIL.msg	Letters and Correspondence	Others	PATIL Amol	January 19, 2018
SCP3858C INSD GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Amol	January 17, 2018
Email received from workshop with TP GIA & estimate.msg	Letters and Correspondence	Others	PATIL Amol	January 17, 2018