Surveyor: Ratbou

REF: III

1228/14 ... 3200c
10E XPIRY: 2022/DEC

ASSIGNMENT

From:	Date: 23/01/18
Estimated Cost:	
OD / TP / WS / TP RES / OD RES / EVA / INV / MV (TP circled)	
To Inspect Vehicle No: SJA 5422J	
at Workshop m/s: Ethoz	
of: 30, Bkt Batok Crescent	
Insured:	
Policy No:	
Claims No:	
Sum Insured:	Excess:
(Client's Record): Mr. Sim	
Make of Veh: After 10 am	
(Policy Condition)	
Remark: The veh had commenced its repair at the time of inspection.	N/S / O/S
Bal. or Market Value:	
IDAC Accident Rport:	Consistent? : Yes or No
GIA / PR Seen:	Consistent? : Yes or No
Est. Repairs: days	Res.: Yes or No
Lum Sum: %	3 Val.: Yes or No
CA / REV / REP. / 24 HRS 'wp'	Vehicle: IN / OUT
Date:	Person Contacted:

Veh No: SJA 5422J	Yr Regn: 2007 DEC
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (M.Car circled)	
Make: Suzuki Swift 1.6 AT	c.c: 1586
Colour: yellow	A/C: Insured / Std / NI / NA
Sp.Reading: 184117	T/Radio: Insured / Std / NI / NA
Eng/No:	
C/No: JSAEZC31S00200765	
Gen. Cond: Good / Fair / Poor / Burnt (Fair circled)	
Steering: Inorder / Jammed / Leaked / Burnt or (Inorder circled)	
Brake: Inorder / Jammed / Leaked / Burnt or (Inorder circled)	
Modi: Nil / S/Rim / STD A/Rim or (S/Rim circled)	
Tyre Size: F: 205/45ZR16	
R:	
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or (PIR circled)	
Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm
D.O.A. 17/01/18	D.O.I. 23/01/18
Survey held at: ETHOZ	
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or: REAR N/S	
The U/C / Chassis frame / Body Structure affected due to collision.	

Date / Time	Action / Instruction

Date/Time, File Pass to? 1)	☐ : Preli. Report	Days Of Repair:	Survey Fee
Date/Time, File Return to? 2)	☐ : Final Report	Resurvey No. of Trip:	Transportation
	Add Fee: ☐ : Site Insp (S$		S + P$ S)
	☐ : Interview (S$		Photos
Report Format :	☐ : Tech. Invs (S$		Others
Lump Sum / I.B.I: (S$	☐ : Weekend (S$		TOTAL