

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64521690

Date : 24/01/2018

QUOTATION -THIRD PARTY CLAIM

AIG ASIA PACIFIC INSURANCE PTE LTD

Attn: Motor Claim Department, Officer In Charge

Claim : Third Party Claim

Veh. No : PC 7710 H

Model : TOYOTA HIACE

Insured Ins: NTUC INCOME

Accident on : 23/01/2018

QTY	PARTICULARS	AMOUNT	SURVEYOR
	YOUR INSURE : GBA 7831 T		
1	TAILGATE	\$ 2,588.50	BT
1	TAILGATE LOCK	\$ 383.45	
1	TAILGATE CENTER LOGO	\$ 68.00	nee
1	TAILGATE HIACE EMBLEM	\$ 58.00	nee
1	TAILGATE G.L EMBLEM	\$ 55.00	nee
1	TAILGATE OUTER CHROME	\$ 485.00	nee
1	TAILGATE W/SCREEN	\$ 2,850.00	ng.
1	TAILGATE TRIM BOARD	\$ 890.00	
1	TAILGATE WIPER MOTOR	\$ 680.00	nee
1	TAILGATE WIPER ARM	\$ 228.00	nee
1	REAR FENDER RH	\$ 2,122.40	BT
1	REAR FENDER INNER PANEL	REPAIR	
1	REAR FENDER LOWER AIR DUCT	\$ 181.58	
1	TAILLAMP RH	\$ 397.80	nee
2	TAILLAMP INNER CLIPS RH	\$ 40.00	nee
1	TAILLAMP PANEL RH	\$ 685.60	
1	REAR RH CORNER APRON PANEL	\$ 242.30	nee
1	REAR RH CORNER APRON PANEL BRACKET	\$ 98.00	nee
1	END PANEL	\$ 980.50	
1	REAR BUMPER	\$ 617.80	nee
10	REAR BUMPER CLIPS	\$ 45.00	nee
1	REAR BUMPER RH SIDE RETAINER	\$ 141.00	nee
1	REAR BUMPER RH BRACKET	\$ 98.00	nee
1	REAR EXHAUST	\$ 1,112.60	nee
		\$ 15,048.53	
	Less 25%	\$ 3,762.13	
		\$ 11,286.40	
	S/NETT PARTS :		
3 TUBE	REAR W/SCREEN SEALANT	\$ 240.00	nee
1	TAILGATE 70KM/H STICKER	\$ 20.00	nee
1	REAR GLASS SOLAR FLIM	\$ 500.00	X
2 TUBE	REAR FENDER QUARTER GLASS SEALANT	\$ 160.00	nee
	TOTAL :	\$ 920.00	
	TOTAL PARTS :	\$ 11,286.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOEXCEL ENGINEERING PTE LTD

160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64541180

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 11,286.40	
	<u>LABOUR :</u>		
	Labour charges	\$ 2,200.00	1200
	To do spray paint on affected area, inner & outer	\$ 1,800.00	1000
	To remove refix, garnish, trim board, garnish upholstery, car seat, belt garnish, floor panel cushion etc	\$ 500.00	80
	Transfer tailgate parts to another tailgate	\$ 140.00	
	Check wiring system, for accident affected area	\$ 15.00	
	Anti rust	\$ 120.00	60
	To do sealant, seal gap, waterproofing for accident affected area	\$ 250.00	120
	Replace rear w/screen and side fender w/screen	\$ 300.00	120
	To replace rear exhaust	\$ 150.00	X
	Labour to repair align side chassis body alignment	\$ 350.00	X
	LABOUR :	\$ 5,825.00	
	TOTAL PARTS & LABOUR :	\$ 17,111.40	

Not Author
H.S. Roger
Reck after petrol photo
H.S. Author

25/1/2018

CRIC Auto

row plays