Repair Estimate

CarCrafters

CarCrafters Singapore Pte Ltd
48 Toh Guan Road East
#05-155, Enterprise Hub
Singapore 608586
Tel: 6267 9916
Fax: 6267 9313
www.carcrafters.sg

India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

Date : 29/1/2018
Vehicle Num : SKL3239R
Make/Model : AUDI A5 2.0 SPORTBACK
Chassis No : WAUZZZ8T2DA064716
Engine No : CDN332677

Our Client,
LEE KUM LING

S/N	PARTS	QTY	PRICE	TOTAL
1	*FRONT BUMPER*	1	$ 1,800.00	$ 1,800.00
2	*FRONT FENDER LH*	1	$ 576.00	$ 576.00
3	*HEADLAMP LH*	1	$ 1,440.00	$ 1,440.00
4	*FOGLAMP LH*	1	$ 180.00	$ 180.00
5	*COOLING AIR GRILLE LH*	1	$ 153.00	$ 153.00
6	*HEADLAMP MOUNTING LH*	1	$ 99.00	$ 99.00
7	*LOCK CARRIER*	1	$ 576.00	$ 576.00
8	*FRONT BUMPER GUIDE PIECE LH*	1	$ 33.00	$ 33.00
9	*WHEELHOUSING LINER LH*	1	$ 135.00	$ 135.00
10	*HEADLAMP WASHER COVER LH*	1	$ 45.00	$ 45.00
11	*HEADLAMP NOZZLER LH*	1	$ 207.00	$ 207.00
12	*NOZZLER BRACKET LH*	1	$ 27.00	$ 27.00
			TOTAL AMOUNT	$ 5,271.00
	LABOUR			
1	To remove/ replace/ refit of front portion of realigned front			$ 1,000.00
	bumper, reinforcement, bonnet, front fender LH & other area.			
2	To putty & respray front bumper, front fender LH,			$ 1,000.00
	bonnet & other affected accident area.			
3	To check accident affected wiring system & recover.			$ 50.00
4	To recode & decode engine management system & fault code			$ 100.00
	clearing after repair works.			
	TOTAL			$ 7,421.00
	GST 7%			$ 519.47
	GRAND TOTAL			$ 7,940.47

SCR
R
X
X
X
X
X
X
X
SCR
X
X
SUC
SUC

1845
10%
1660.5

250
500
750

X 11
X 11

1660.50
750.00
2410.50
20%
1928.40
4S - 1,900

RASUL
Hp 90010068
3 days
4S
Resurvey after repair
30/01/18 @ 11 o'clock

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3 days