REF: III

ASSIGNMENT

From: Date: 30/1/18

Estimated Cost:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS9289H

at Workshop m/s: ~~Tan Lim~~ Motor Pegasus

of: 51 Defu Lane 10

Insured:

Policy No: SMD 4625E

Claims No:

Sum Insured: Excess:

(Client's Record): 10.30 am @ owner waiting

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S | O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

(GIA) / PR Seen: ✓ Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLS9289H Yr Regn: 10/17

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (A)

Make: Honda Vezel Hybrid 1496

Colour: Silver A.C.: Insured / Std / NI / NA

Sp.Reading: 31661 T.Radio: Insured / Std / NI / NA

Eng No:

C/No: RU3-1247338

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (Intact) / Jammed / Leaked / Burnt or

Brake: (Intact) / Jammed / Leaked / Burnt or

Modi: Nil / (Skirts) / STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS / (DUN) / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 25/1/18 D.O.I. 30/1/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time | Action / Instruction

Date/Time File Pass to: [ ] : Prell. Report

[ ] : Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee: [ ] Site Insp. $

[ ] Interview $

[ ] Techn... $

[ ] Weekend $

Report Format:

Lump Sum:

TOTAL