# LBA AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47
AUTOBAY SINGAPORE 417883
Tel : 6509 5521 / 65095524 Fax : 6509 5523

LKK Auto ... Survey
... Prejudice" basis
... and
... Insurance Company
Acknowledge by repairer
Signature

## ESTIMATE

DATE : 29.01.2018
VEHICLE NO : GBD7544G
MAKE/MODEL : TOYOTA DYNA
ACC DATE : 27.01.2017

The Motor Claims Dept.
**CHINA TAIPING INSURANCE (S) PTE LTD**
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
**SJN9401A**

Not Agreed
Nil
a/c $5500/-
6 day.
30/1/18
Take photo After Repair

| | QTY | PARTICULAR | UNIT PRICE S$ | | AMOUNT S$ |
|---|---|---|---|---|---|
| | | **LIST PRICE** | | | |
| 1 | 1 | FRT WINDSCREEN RUBBER | 297.40 | nil | 297.40 |
| 2 | 1 | FRT PANEL | 1,100.30 | Sent by DD | 1,100.30 |
| 3 | 1 | FRT PANEL STICKER 'DYNA' | 74.10 | nil | 74.10 |
| 4 | 1 | FRT PANEL CENTRE GARNISH | 258.45 | " | 258.45 |
| 5 | 1 | FRT GRILLE | 517.45 | nil | 517.45 |
| 6 | 1 | FRT GRILLE EMBLEM 'LOGO' | 85.90 | nil | 85.90 |
| 7 | 1 | FRT GRILLE RUBBER SEAL | 103.20 | To. | 103.20 |
| 8 | 1 | FRT CORNER PANEL RH | 330.45 | 20 | 330.45 |
| 9 | 1 | FRT CORNER GARNISH RH (BOTTOM) | 99.85 | nil | 99.85 |
| 10 | 1 | FRT CORNER GARNISH RH (TOP) | 230.60 | " | 230.60 |
| 11 | 1 | FRT HEADLAMP RH | 868.00 | 3rd | 868.00 |
| 12 | 1 | FRT HEADLAMP LOWER RUBBER RH | 35.30 | To. | 35.30 |
| 13 | 1 | FRT BUMPER | 755.90 | Tw | 755.90 |
| 14 | 2 | FRT BUMPER BRACKET RH/LH | 161.45 | " | 322.90 |
| 15 | 1 | FRT BUMPER FOG LAMP RH | 310.40 | " | 310.40 |
| 16 | 1 | FRT BUMPER FOG LAMP0 COVER RH | 127.40 | sent | 127.40 |
| 17 | 1 | FRT DOOR RH | 1,528.70 | 20/Sept | 1,528.70 |
| 18 | 1 | FRT DOOR TOP HINGE RH | 115.30 | Sept | 115.30 |
| 19 | 1 | FRT DOOR RUBBER | 198.05 | nil | 198.05 |
| 20 | 1 | FRT DOOR SIGNAL LAMP | 88.30 | cro | 88.30 |
| 21 | 1 | CHASSIS FRONT CROSSMEMBER | 426.50 | " | 426.50 |
| | | | | | 7,874.45 |
| | | LESS 25% | 6325.6 | | 1,968.61 |
| | | | 4744.20 | | 5,905.84 |
| | | **SPECIAL NETT ITEMS** | | | |
| 1 | 1 | FRT DOOR LETTERING STICKER | 25.00 | nil | 25.00 |
| | | **LABOUR CHARGES :** | | | |
| 1 | | TO KNOCK OUT DENT, CUT/WELD FRONT PANEL, FRONT CHASSIS CENTRE CROSS MEMBER AND REPLACE ACCIDEN PARTS | | 800 | 1,000.00 |
| 2 | | TO SPRAY PAINTING ON ACCIDENT PORTION | | 900 | 1,200.00 |
| 3 | | TO CHECK WIRING | | 20 | 30.00 |
| 4 | | TO REMOVE, REFIX WINDSCREEN | | 60 | 120.00 |
| 5 | | TO REMOVE, REFIX DASHBOARD | | 160 | 280.00 |
| 6 | | TO REMOVE, REFIX AIR CON BLOWER AND REFILL GAS | | 100 | 100.00 |
| 7 | | TO TUFF KOTE | | 80 | 90.00 |
| | | | | | 2,820.00 |
| | | | | 6881.2 | |

**ESTIMATE PARTS AND LABOUR GRAND TOTAL : $ 8,750.84**