LKK/Kalvin L/Sum

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7684U

DATE 31/1/2018 9:47

LKC AIG

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) X repair			$ 1,935.90
	Rear Fender Inner Lining (RH) X			$ 74.10
	Rear Windscreen Moulding X			$ 60.00
	Rear Wheel Hub Cap			$ 145.00
	SUB TOTAL			**$ 2,215.00**
	LESS 20%			$ 443.00
	DISCOUNTED TOTAL			**$ 1,772.00**
	Rear Windscreen Sealant X			$ 46.00 Nett
				$ 46.00
	Labour Charge			
	Panel Beating			$ ~~560.00~~ 200
	Spray Painting Charge			~~400~~ $ ~~200.00~~ 360
	Wiring Charge			$ ~~50.00~~ X
	Remove/Refix Reverse Sensor			$ ~~120.00~~ X
	Rear Wheel Alignment			$ ~~80.00~~ X
	TOTAL LABOUR			**$ 1,010.00**
	ESTIMATE TOTAL			**$ 2,828.00**

Kalvin LKK
31/1/18 1415 hrs.
2 Pgs.
4s
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledgement
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.