Survey No: REF: A1G

ASSIGNMENT

From: Date: 20/02/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 3788K

at Workshop m/s: Esteem Performance

of: Blk 5033, AMK Ind. Prk 2 #01-259

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record): 11am owner waiting

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: PC 3788K Yr Reg: 07 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toy Hiace c.c.: 2982

Colour: White / Blue A/C: Insured / Std / NI / NA

Sp.Reading: 91975 T/Radio: Insured / Std / NI / NA

Eng No:

C/No: JTFHT02P 6 00157737

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoperr / Jammed / Leaked / Burnt or

Brake: Inoperr / Jammed / Leaked / Burnt or

Modi: NIL / S/Rim / STD A/Rim or

Tyre Size F: 195 R 15 x 8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Max Miler

Front		Rear	
R/Bal.	9 mm	R/Bal.	9 mm
L/Bal.	9 mm	L/Bal.	9 mm

D.O.A. 9/1/18 D.O.I. 20/2/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
21/2	file pass to Denise

Date/Time File Pass to: : Preli. Report

: Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: Site Insp. / S

Interim / S

Tech. / S

Meeting / S

Report Format:

Lump Sum / I.B.I. / S

Survey Fee

Transportation

Photos

Other

Total