

ASS. REC. BY:

REF CS/MSG18002337/49d3ez

Special Instruction

Surveyor

Meinren

Marcus

ASSIGNMENT (Office)

From (Person)

Winnie Chua

of

MSG

Date/Time

6/2/18 @ 10:20am

Estimated Cost:

Bill to:

①

TP / WS / TP RES / OL RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EW 313S

Insured:

at Workshop m/s

Falcon-Air-Auto

Tel:

67897997

of

Tampines St. 93, Blk 9006 #01-200

Policy No:

A271717170MX

Claim No:

518704

Sum Insured:

Excess:

\$1,000.00

Make of Veh:

(Client's Record)

D.O.A.

05/02/2018

CA / (REV)

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:06am @ 6/2/18

Person Contacted:

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	EW 313S - X
07/7/18 @ 3:29pm	revert to Winnie Chua via Meinren.
08/7/18 @ 8:41am	Siew Wei informed C/A via Meinren.
08/7/18 @ 3:04pm	informed Janet C/A S ex: \$1000 by email.
13/7/18 @ 4:57pm	revert to Winnie Chua via Meinren. (Supplementary)
17/7/18 @ 11:22am	Siew Wei informed C/A at 63307 via Meinren.

(08/11/73) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: EW 3135at Workshop m/s Helcon

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 1000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 3000

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 1.81 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: EW3135 Yr Regn: 9, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /Make: Toyota Estime c.c. 2362Colour: white A/C: Insured / Std / NI / NASp. Reading: 99591 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACR500095719Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55-17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 5/1/18 D.O.I. 6/2/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s h.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 17422331

22/3/18 next 7669
 Confirmed final of 3307 with Joel
 (Red 5 1278.50, 28/6/18)
 no lump sum

RECEIVED 18 MAR 2018

Date/Time, File Pass to?

1) 24/3/18 hmsa

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: MEMOLump Sum / I.B.I. (\$) 3307

TOTAL

200

20

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002337/Uqd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 06-02-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	EW 313S
Policy No.	A27171717QMX	Coverage (\$)	0.00
Claim No.	548704	Excess (\$)	1,000.00
Assign From	MERIMEN (WINNIE CHUA)	Assign Date	06/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/02/2018	Inspection Date	06/02/2018
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018 Sendback Est	06 Feb 2018 09:58 S\$4,585.50	06 Feb 2018 10:20 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	THAM LAI PING WINNIE, ID: S1467548E, Tel: +6596936436		
Vehicle Reg. No.:	EW313S	Date of Loss:	05/02/2018 09:00 - :59
Claim Type:	OD / 548704	Policy/Cover Note No.:	A27171717QMX (Comprehensive) Coverage: 12/09/2017 - 11/09/2018
		Excess:	S\$1,000.00
Repairer:	Falcon-Air Auto Services Pte Ltd (Tampines) Tampines St 93 Blk 9006 #01-200, Tampines - Tel: 67897997		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping Ping - 6594 2556]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/02/2018]		
Driver/Custodian:	LIM EE ANN (60 / Male), NRIC: S1278611E, Tel: +6596791491		
Adj Asg. Remarks:	Please revert. tks. car in already. urgent.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Feb 2018 09:36	Clim Veh Model Changed	(201141) TOYOTA ESTIMA 2.4 (A).	[R] Joel Ng
2	06 Feb 2018 09:36	Clim Created	Reg No: EW313S. Policy No: A27171717QMX. Acct Date: 2018/02/05. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Falcon-Air Auto Services Pte Ltd (Tampines). Created from SAS:MFA318018120	[R] Joel Ng
3	06 Feb 2018 09:58	Clim Submitted	4585.50.	[R] Joel Ng
4	06 Feb 2018 10:07	Clim Registration Modified	Excess: -> 1000.00.	[I] Winnie Chua Ping Ping
5	06 Feb 2018 10:20	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert. tks. car in already. urgent.	[I] Winnie Chua Ping Ping
6	06 Feb 2018 10:20	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/02/07	[I] Winnie Chua Ping Ping
7	06 Feb 2018 10:20	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Winnie Chua Ping Ping
8	06 Feb 2018 10:52	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	06 Feb 2018 15:22	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Nivitha Govindasamy
10	07 Feb 2018 15:26	Adj Rpt Initiated		[A] SHIAU CHAN
11	07 Feb 2018 15:28	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/08	[A] SHIAU CHAN
12	07 Feb 2018 15:28	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/08	[A] SHIAU CHAN
13	07 Feb 2018 15:29	Adj Mandate Request	Cur.Req:3261.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
14	08 Feb 2018 08:41	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/08. Mandate Remarks: a if c; check items to be confirmed	[I] Lui Siew Wei
15	08 Feb 2018 08:41	Adj Mandate Set	Approved:2948.00:a if c; check items to be confirmed	[I] Lui Siew Wei
16	22 Feb 2018 14:05	Clim Supp Created (S:685967)		[R] Joel Ng
17	22 Feb 2018 14:06	Clim Submitted (S:685967)	60.50.	[R] Joel Ng
18	22 Feb 2018 14:06	Adj Co Assigned (S:685967)	LKK Auto Consultants Pte Ltd (HQ):	[I] Merimen Administrator
19	14 Mar 2018 08:58	Supp Combined (S:685967)		[A] SHIAU CHAN
20	23 Mar 2018 16:56	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/08	[A] SHIAU CHAN
21	23 Mar 2018 16:57	Adj Mandate Request	Cur.Req:3307.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
22	27 Mar 2018 11:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/08. Mandate Remarks: a if c	[I] Lui Siew Wei
23	27 Mar 2018 11:22	Adj Mandate Set	Approved:3307.00:a if c	[I] Lui Siew Wei

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1716245	06/02/2018 09:36	Motor	Falcon-Air Auto Services Pte Ltd (HQ)	Falcon-Air Auto Services Pte Ltd (Tampines)	EW313S		xx.xx
1718248	07/02/2018 15:26	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	EW313S		10.70
1735433	06/02/2018 09:46	Motor	MSIG Insurance (Singapore) Pte. Ltd.	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	EW313S	548704	xx.xx

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 23 Mar 2018

Preliminary Advice

Vehicle No	: EW313S	Accident Date	: 05/02/2018
Make	: TOYOTA ESTIMA	Policy No.	: A27171717QMX
Assignment Date	: 06/02/2018	Excess	: S\$1,000.00
Date of Inspection	: 06/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES) TAMPINES ST 93 BLK 9006 #01-200 SINGAPORE		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,646.00	(ESTIMATE \$4,585.50 + SUPPLEMENTARY \$60.50)
Revised Amount	:S\$	3,307.00	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	3,307.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	30,000.00
COE / PARF Rebate	:S\$	22,331.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,669.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 8 February 2018 3:04 PM
To: janet@falconair.com.sg
Cc: SUR
Subject: VEHICLE EW 313S (DOA: 05/02/2018)

Dear Janet,

As spoken with you.

As instructed by our client MSIG Insurance, please proceed to repair the insured vehicle **EW 313S (Excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				By
No.	On	Audit	Remarks	
1	06 Feb 2018 09:36	Clim Veh Model Changed	(201141) TOYOTA ESTIMA 2.4 (A). Reg No: EW313S. Policy No: A27171717QMX. Acct Date: 2018/02/05. Claim Ty pe: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Falcon -Air Auto Services Pte Ltd (Tampines). Created from SAS:MFA318018120	[R] Joel Ng
2	06 Feb 2018 09:36	Clim Created		[R] Joel Ng
3	06 Feb 2018 09:58	Clim Submitted	4585.50.	[R] Joel Ng
4	06 Feb 2018 10:07	Clim Registration Modified	Excess: -> 1000.00.	[I] Winnie Chua Ping Ping
5	06 Feb 2018 10:20	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert. tks. car in already. urgent.	[I] Winnie Chua Ping Ping
6	06 Feb 2018 10:20	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/02/07	[I] Winnie Chua Ping Ping
7	06 Feb 2018 10:20	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Winnie Chua Ping Ping
8	06 Feb 2018 10:52	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	06 Feb 2018 15:22	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Nivitha Govindasamy
10	07 Feb 2018 15:26	Adj Rpt Initiated		[A] SHIAU CHAN
11	07 Feb 2018 15:28	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/08	[A] SHIAU CHAN
12	07 Feb 2018 15:28	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/08	[A] SHIAU CHAN
13	07 Feb 2018 15:29	Adj Mandate Request	Cur.Req:3261.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HA VE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
14	08 Feb 2018 08:41	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/08. Mandate Remarks: a if c; check item s to be confirmed	[I] Lui Siew Wei
15	08 Feb 2018 08:41	Adj Mandate Set	Approved:2948.00:a if c; check items to be confirmed	[I] Lui Siew Wei

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1716245	06/02/2018 09:36	Motor	Falcon-Air Auto Services Pte Ltd (HQ)	Falcon-Air Auto Services Pte Ltd (Tampines)	EW313S		xx.xx
1718248	07/02/2018 15:26	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	EW313S		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 07 Feb 2018

Preliminary Advice

Vehicle No	: EW313S	Accident Date	: 05/02/2018
Make	: TOYOTA ESTIMA	Policy No.	: A27171717QMX
Assignment Date	: 06/02/2018	Excess	: S\$1,000.00
Date of Inspection	: 06/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES) TAMPINES ST 93 BLK 9006 #01-200 SINGAPORE		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,585.50
Revised Amount	:S\$	2,948.00
Check Items (Estimated)	:S\$	313.50
Total	:S\$	3,261.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	30,000.00
COE / PARF Rebate	:S\$	22,331.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,669.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.
WE HAVE NOT AUTHORISE REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7548E
Vehicle Details	
Vehicle No.:	EW313S
Vehicle to be Exported:	No
Intended De-registration Date:	06 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	2AZC668660
Chassis No.:	ACR500095719
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$35,321.00
Original Registration Date:	12 Sep 2009
First Registration Date:	12 Sep 2009
Transfer Count:	0
Actual ARF Paid:	\$35,321.00 17660
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2019
PARF Rebate Amount:	\$19,426.00
Intended COE Rebate Details	
COE Expiry Date:	11 Sep 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,189.00
COE Rebate Amount:	\$2,905.00
Total Rebate Amount:	\$22,331.00

The information contained herein is correct as at 06 Feb 2018

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips



SELL

CAR PARTS & ACCESSORIES *Online!*

CAR

Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New Facelifted Model, Nov 2013 Mercedes-Benz E250.



Cheapest In Market! Fully Serviced By C&C Since Day 1!

Tely Auto Credit StarAd



Think One Automobile & COMMERCIAL



Browse by Category

Sort by Date Posted

20 results/page

9 vehicles

Toyota Estima

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Estima		Any	Any	2009	Any	Any	Any	Available
	Toyota Estima	2.4A X	\$39,800	\$15,050 /yr	29-Aug-2009	2,362 cc	-	MPV	Available
New Aircond Compressor, Good Condition, No Repair Needed, Accident Free. Bank Loan In House Loan Available.									
Posted: 04-Feb-2018 Tags: 2009 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
	Toyota Estima	Hybrid 2.4A X	\$33,800	\$21,160 /yr	09-Jan-2009	2,362 cc	-	MPV	Available
Fuel Type: Petrol-Electric									
Elegant Silver Hybrid MPV, Low Fuel Consumption With Hybrid, With Twin Moonroof. Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In House Loan Packages Available.									
Prime Motor & Leasing									
Posted: 03-Feb-2018 Tags: 2009 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
	Toyota Estima	Hybrid 2.4A X	\$39,800	\$16,830 /yr	28-Aug-2009	2,362 cc	74,500 km	MPV	Available
Fuel Type: Petrol-Electric									
New Road Tax, Excellent Condition, Low Mileage, Accident Free, Bank Loan In House Loan Available. 3 Months Warranty From Our In-house Workshop.									
Posted: 01-Feb-2018 Tags: 2009 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
	Toyota Estima	2.4A X	\$35,800	\$16,100 /yr	15-Jul-2009	2,362 cc	128,000 km	MPV	Available
New Roadtax! Zero Repair Needed And With Service Records History! Original Beautiful Paintwork And Interior! Accident Free! Such Condition Mpv Drive Till End With No Worries Even Worth For Renewing CO...									
Posted: 30-Jan-2018 Tags: 2009 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
Car Buying Car Selling Car Aftermarket Buying a pre-owned car, but Unsure of its Condition? Car Ownership On The Move Lifestyle Get, STA Car Evaluation									
	Toyota Estima	2.4A Aeras Premium Moonroof	\$35,000	\$15,230 /yr	30-Mar-2009	2,362 cc	245,155 km	MPV	Available
Posted: 28-Jan-2018 Tags: 2009 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
	Toyota Estima	2.4A Aeras	\$44,800	\$15,270 /yr	25-Nov-2009	2,362 cc	-	MPV	Available
Most Sought AFTER MPV! Popular 7 Seater Model With 2 x Power Doors And Sunroof. High OMV Value And High Body Value Upon Scrap. Low Mileage Done At 15K Km Yearly. A Spacious MPV Surely Worth Every Doll...									
Posted: 24-Jan-2018 Tags: 2009 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota									
Compare Toyota Estima 2.4A \$29,800 \$15,240 /yr 22-Jan-2009 2,362 cc 109,000 km MPV Available									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2018 08:44
Date Of Accident	05/02/2018 09:30
Exact Location Of Accident	JUNCTION OF JALAN MASJID / CHANGI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EW313S
Insured/Policyholder	
Name Of Registered Owner	THAM LAI PING WINNIE
NRIC No	S1467548E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96936436
Alternative Phone No	OFFICE-96936436

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA-2.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO


Policy Number

Cover Note Number

Driver

Name of Driver	LIM EE ANN
NRIC No	S1278611E
Date Of Birth	25/12/1957
Occupation	INDOOR
Date Of Driving Pass	19/11/1975
Driving Experience	42 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96791491
Fax Number	
Contact Number	
EMail Address	EEALIM@GMAIL.COM

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was following behind the vehicle GAD8618X along Jalan Masjid going towards the junction. As the Van had move off from the junction, I also move out slowly and I was checking for the traffic on my left for assurance. As traffic was clear I accelerate and turn my head suddenly the vehicle make a sudden stop upon seeing I also immediately step on my brakes but was too late therefore a collision occur.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: FALCON-AIR AUTO SERVICES PTE LTD(TP)-2

BLK 9006 TAMPINES ST 93

#01-200

SINGAPORE 528840

NO: DL19199510

PAGE: 1

DATE: 07-02-2018

A/C CODE: LDF-A143

TERMS: CR

VEH NO: BW 3135

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
T81211-42050	FOG LAMP RH	DLS	1	85.00	85.00
TOTAL QUANTITY:			1	TOTAL	SIN 85.00
				ADD GST @ 7%	5.95
				GRAND TOTAL	SIN 90.95


Print: LIM: 07-02-2018 9:03:55 AM

SALESMAN: LIM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

1620





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: FALCON-AIR AUTO SERVICES PTE LTD(TP) 2

BLK 9006 TAMPINES ST 93

#01-200

SINGAPORE 528840

NO: DL19199485

PAGE: 1


DATE: 06/02/2018

A/C CODE: LDFA143

TERMS: CR

VENUE: LVS-135

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T81481-28270	BKT FOG LAMP RH	DUIAB32-2	1	55.00	55.00
2 T81481-28290	COVER FOG LAMP RH	DUIAB32-2	1	40.00	40.00
TOTAL QUANTITY			2	TOTAL	SIN 95.00
				ADD GST @ 7%	6.65
				GRAND TOTAL	<u>SIN 101.65</u>






Print: LIM / 06/02/2018 2:17:20 PM

SALESMAN: LIM

This document is computer generated. No signature required.

GOODS SOLD AS IS. NOT RETURNABLE





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: FALCON AIR AUTO SERVICES PTE LTD (1P) 2

BLK 9006 LAMPINES ST 93

#01-200

SINGAPORE 528840

NO: D119199482

PAGE: 1

DATE: 06.02.2018

A/C CODE: L10FA143

TERMS: CR

VAT NO: EW3135

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T52119-28973 ✓	BUMPER LK	DB20	1	220.00	220.00
2 T52115-28170	BUMPER RETAINER FR RH	DB1AD30-2	1	25.00	25.00
3 T53811-28091 ✓	FENDER FR RH	DB1B30	1	175.00	175.00
4 T53805-28041	FENDER LINER FR RH	DB1B10	1	85.00	85.00
5 T53301-28110	BONNET	DB1B45	1	180.00	180.00
6 T85315-28230	WASHER TANK	DB1AB5-3	1	45.00	45.00
7 T90981-20024 ✓	BULB-HID	DB1A98	1	160.00	160.00
8 T81145-28C70	HEADLAMP RH	DDS	1	550.00	550.00
TOTAL QUANTITY			8	TOTAL	SIN 1,440.00
				ADD GST @ 7%	100.80
				GRAND TOTAL	SIN 1,540.80

Print / LIM / 06/02/2018 2:35:46 PM

SALESMAN: LIM

This document is computer generated. No signature required

GOODS SOLD ARE SOLELY RETURNABLE





FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. No.: 199501140-D

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A27171717QMX	Date of Loss:	05/02/2018
Vehicle Reg. No.:	EW313S	Driveable?	
Driver Age/Info:	60 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	THAM LAI PING WINNIE	Contact No:	+6596936436
Driver:	LIM EE ANN		
Make/Model:	TOYOTA ESTIMA, 2.4 (A)	Vehicle Reg. Date:	12/09/2009
Vehicle Colour:	PEARL WHITE		
Engine No:	2AZC668660	Chassis No:	ACR500095719
Odometer:	100000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	AS PER SKETCH PLAN ATTACH.		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

not Belhorm
blue
tel. 62583561
Excess \$1000
5 day.

6/2/18
Take photo before repair.

COST OF CLAIMS

Parts	<i>Tax: 62564315</i>	Amount
Miscellaneous Items		2,235.50
Labour		0.00
Paintwork Labour		2,350.00
Towing		0.00

- LKH Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

This claim is handled by: JOEL NG

Signature:

Calculated Gross Total (\$\$)	4,585.50
- Excess (\$\$)	1,000.00
(\$\$)	3,585.50
+ GST 7.00% (\$\$)	250.99
Nett Amount (\$\$)	3,836.49

Generated using Merimen e-Claims Internet Estimation & Adjusting System

p/p \$3307

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Feb 2018)

Parts: M1-MPV TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/EW313S/06/02/2018 09:58

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER <i>DS</i>	0.00	0.00	*220.00 F	✓
2	2		*FRONT BUMPER SIDE RETAINER <i>o/s car</i>	0.00	0.00	*50.00 F	100
3	10		*FRONT BUMPER CLIPS <i>ru</i>	0	0.00	*15.00 FS	✓
4	1		*O/S HEADLAMP UNIT <i>B20</i>	0.00	0.00	*550.00 F	✓
5	1		*O/S HEADLAMP HID BULB <i>Dange</i>	0.00	0.00	*160.00 F	2
6	1		*O/S HEADLAMP HID BALAST <i>11</i>	0.00	0.00	*250.00 F	X
7	1		*O/S FRONT FENDER <i>Luc</i>	0.00	0.00	*175.00 F	✓
8	1		*O/S FRONT FENDER INNER SHIELD <i>Yoin</i>	0.00	0.00	*85.00 F	✓
9	10		*O/S FRONT FENDER INNER SHIELD CLIPS <i>NA</i>	0	0.00	*15.00 FS	4
10	1		*BONNET <i>o/s car</i>	0.00	0.00	*180.00 F	✓
11	1		*RADIATOR GRILLE <i>11</i>	0.00	0.00	*140.00 F	✓
12	1		*RADIATOR GRILLE LOGO <i>11</i>	0.00	0.00	*25.00 F	✓
13	1		*O/S FOGLAMP <i>C12</i>	0.00	0.00	*85.00 F	✓
14	1		*O/S FOGLAMP GARNISH <i>one</i>	0.00	0.00	*40.00 F	✓
15	1		*WASHER TANK <i>22</i>	0.00	0.00	*45.00 F	✓

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,035.00
+ Margin on L,N Items 10.00% (S\$)	200.50
Total Parts (S\$)	2,235.50

Falcon-Air Auto Services Pte Ltd/EW313S/06/02/2018 09:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1620
102
1782
3292

S.N 15
3307

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK WIRING	New 20	50.00
2	TO REINSTALL SENSOR, RESET SONAR CLEARANCE AND HID BULD WITH DIAGNOSTIC	New 40	280.00
3	LABOUR/PANEL BEATING (REPAIR SUPPORT PANEL, O/S FRT WHEELHOUSE)	New 550	700.00
4	SPRAY PAINTING 1)OS FRT DOOR, 2)OS FRT FENDER 3)FRT BUMPER 4)OS WHEELHOUSE PANEL 5)SUPPORT PANEL 6)BONNET	New 900	1,200.00
5	TO VACUUM, REOIL AND REGAS AIRCON	New 11	120.00
Gross Labour Cost (S\$)			2,350.00

Falcon-Air Auto Services Pte Ltd/EW313S/06/02/2018 09:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(Incorporated in Singapore)

Head Office: BA 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches: Tampines St 93 Bk 9000 #01-200 S(526840) Tel: 6789-7997 Fax: 6789-7997 • No 8 Pandan Loop S(125226) Tel: 6779-5865 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

1510

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 22 Feb 2018)**Parts:** M1-MPV TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Falcon-Air Auto Services Pte Ltd/EW313S/22/02/2018 14:06**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*O/S FOGLAMP BRACKET <i>cm</i> <i>add</i>	0.00	0.00	*55.00 F ✓
						Sub Total (\$)
						55.00
						+ Margin on L,N Items 10.00% (\$)
						5.50
						Total Parts (\$)
						60.50

Falcon-Air Auto Services Pte Ltd/EW313S/22/02/2018 14:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Feb 2018 Sendback Est	06 Feb 2018 09:58 S\$4,585.50	06 Feb 2018 10:20 Edit Adj Rpt	S\$3,307.00 Edit Estimates	S\$3,307.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	22 Feb 2018 14:05	22 Feb 2018 14:06 S\$60.50	22 Feb 2018 14:06			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	THAM LAI PING WINNIE , ID: S1467548E, Tel: +6596936436		
Vehicle Reg. No.:	EW313S	Date of Loss:	05/02/2018 09:00 - :59
Claim Type:	OD / 548704	Policy/Cover Note No.:	A27171717QMX (Comprehensive) Coverage: 12/09/2017 - 11/09/2018
		Excess:	S\$1,000.00
Repairer:	Falcon-Air Auto Services Pte Ltd (Tampines) Tampines St 93 Blk 9006 #01-200, Tampines - Tel: 67897997		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping Ping - 6594 2556]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/03/2018]		
Driver/Custodian:	LIM EE ANN (60 / Male), NRIC: S1278611E, Tel: +6596791491		
Adj Asg. Remarks:	Please revert. tks. car in already. urgent.		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- MSIG_SG (27/03/2018): Alert - Adj Mandate Approved (S\$3307.00) - EW313S - Claim Handler: Winnie Chua P...
- MSIG_SG (08/02/2018): Alert - Adj Mandate Approved (S\$2948.00) - EW313S - Claim Handler: Winnie Chua P...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

EW313S (548704)
OD
Feb 5 2018 9:00AM
[THAM LAI PING WINNIE]
Falcon-Air Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser v		
Assessment Reports			1 per page v	☒	
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)		Thumbnail	Print
1	06/02/18 09:01	Accident Statement		Load HTM	
2	06/02/18 09:58	Repairer Estimates		Load HTM	
3	22/02/18 14:06	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/02/18 15:28	Adjuster Immediate Advice		Load HTM	
2	23/03/18 16:56	Adjuster Immediate Advice		Load HTM	
Photos/Images			3 per page v	☒	
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)		Thumbnail	Print
1	06/02/18 08:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	06/02/18 08:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	06/02/18 08:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	06/02/18 08:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	06/02/18 08:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	06/02/18 08:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	06/02/18 08:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	06/02/18 08:48	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	06/02/18 09:00	Identification Card [Linked Accident Report Documents]		Load JPG	☒
10	06/02/18 09:00	Identification Card [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/02/18 19:33	Chassis Number		Load JPG	☒
2	06/02/18 19:33	General View		Load JPG	☒
3	06/02/18 19:33	Odometer Reading		Load JPG	☒
4	06/02/18 19:33	General View		Load JPG	☒
5	06/02/18 19:33	General View		Load JPG	☒
6	06/02/18 19:33	General View		Load JPG	☒
7	06/02/18 19:33	General View		Load JPG	☒
8	06/02/18 19:33	General View		Load JPG	☒
9	06/02/18 19:33	General View		Load JPG	☒
10	06/02/18 19:33	General View		Load JPG	☒
11	06/02/18 19:33	General View		Load JPG	☒
12	06/02/18 19:33	General View		Load JPG	☒
13	06/02/18 19:33	General View		Load JPG	☒
14	06/02/18 19:33	General View		Load JPG	☒
15	06/02/18 19:33	General View		Load JPG	☒

16	06/02/18 19:33	General View	1	Load JPG	☒
17	06/02/18 19:33	General View	1	Load JPG	☒
18	06/02/18 19:33	General View	1	Load JPG	☒
19	06/02/18 19:33	General View	1	Load JPG	☒
20	06/02/18 19:33	General View	1	Load JPG	☒
21	06/02/18 19:33	General View	1	Load JPG	☒
22	06/02/18 19:33	General View	1	Load JPG	☒
23	06/02/18 19:33	General View	1	Load JPG	☒
24	06/02/18 19:33	General View	1	Load JPG	☒
25	06/02/18 19:33	General View	1	Load JPG	☒
26	06/02/18 19:33	General View	1	Load JPG	☒
27	06/02/18 19:33	General View	1	Load JPG	☒
28	06/02/18 19:33	General View	1	Load JPG	☒
29	06/02/18 19:33	General View	1	Load JPG	☒
30	06/02/18 19:33	General View	1	Load JPG	☒
31	06/02/18 19:33	General View	1	Load JPG	☒
32	06/02/18 19:33	General View	1	Load JPG	☒
33	06/02/18 19:33	General View	1	Load JPG	☒
34	06/02/18 19:33	General View	1	Load JPG	☒
35	06/02/18 19:33	General View	1	Load JPG	☒
36	06/02/18 19:33	General View	1	Load JPG	☒
37	06/02/18 19:33	General View	1	Load JPG	☒
38	06/02/18 19:33	General View	1	Load JPG	☒
39	06/02/18 19:33	General View	1	Load JPG	☒
40	06/02/18 19:33	General View	1	Load JPG	☒
41	06/02/18 19:33	General View	1	Load JPG	☒
42	06/02/18 19:33	General View	1	Load JPG	☒
43	06/02/18 19:33	General View	1	Load JPG	☒
44	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
45	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
46	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
47	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
48	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
49	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
50	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
51	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
52	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
53	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
54	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
55	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
56	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
57	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
58	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
59	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
60	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
61	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
62	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
63	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒
64	08/02/18 17:40	Reinspection Photo	1	Load JPG	☒

Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/18 15:28	ESTIMATE	 Load PDF	
2	23/03/18 16:59	SUPPLEMENTARY LIST	 Load PDF	
3	02/04/18 12:34	Parts Invoice	 Load PDF	

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)	Thumbnail	Print
1	06/02/18 09:01	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)	Thumbnail	Print
1	06/02/18 08:48	Accident Photo	 Load JPG	☒
2	06/02/18 08:48	Accident Photo	 Load JPG	☒
3	06/02/18 08:48	Accident Photo	 Load JPG	☒
4	06/02/18 08:48	Accident Photo	 Load JPG	☒
5	06/02/18 08:48	Accident Photo	 Load JPG	☒
6	06/02/18 08:48	Accident Photo	 Load JPG	☒
7	06/02/18 08:48	Accident Photo	 Load JPG	☒
8	06/02/18 08:48	Accident Photo	 Load JPG	☒
9	06/02/18 09:00	Identification Card	 Load JPG	☒
10	06/02/18 09:00	Identification Card	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)	Thumbnail	Print
1	06/02/18 09:00	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18002337/UQD3E2

Date: 02/04/2018

REFERENCE

Insured/Claimant: THAM LAI PING WINNIE Policy No: A27171717QMX
Date of Loss: 05/02/2018 Nature of Claim: OD Claim No: 548704

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EW313S**
Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZC668660
Reg. Date: 12/09/2009 (Man. Year: 2009) Chassis No: ACR500095719
Colour: White Odometer: 89591 km
Engine Capacity: 2362 cc
Market Value/New Car Price: S\$30,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,296.00	1,797.00	499.00	21.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,510.00	840.00	35.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,646.00	3,307.00	1,339.00	28.82
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	3,646.00	2,307.00	1,339.00	36.73
+ GST 7.00/7.00% (S\$)	255.23	161.49	93.74	36.73
Nett Amount (S\$)	3,901.23	2,468.49	1,432.74	36.73

INSPECTION

Date of Assignment: 06/02/2018 Present Location: Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected: 06/02/2018 Inspected At: Tampines St 93 Blk 9006 #01-200 Singapore
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Apr 2018)
Parts: M1-MPV TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for EW313S)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Distorted	220.00 F	*220.00 F
2	1		*FRONT BUMPER SIDE RETAINER (WCP)	O/S Cracked	50.00 F	*25.00 F
3	10		*FRONT BUMPER CLIPS (WCP)	Necessary	15.00 FS	*15.00 FS
4	1		*O/S HEADLAMP UNIT (WCP)	Broken	550.00 F	*550.00 F
5	1		*O/S HEADLAMP HID BULB (WCP)	Damaged	160.00 F	*160.00 F
6	1		*O/S HEADLAMP HID BALAST (WCP)	Not Necessary	250.00 F	*- F
7	1		*O/S FRONT FENDER (WCP)	Buckled	175.00 F	*175.00 F
8	1		*O/S FRONT FENDER INNER SHIELD (WCP)	Torn	85.00 F	*85.00 F
9	10		*O/S FRONT FENDER INNER SHIELD CLIPS (WCP)	Not Necessary	15.00 FS	*- FS
10	1		*BONNET (WCP)	Dented / Bent	180.00 F	*180.00 F
11	1		*RADIATOR GRILLE (WCP)	Not Necessary	140.00 F	*- F
12	1		*RADIATOR GRILLE LOGO (WCP)	Not Necessary	25.00 F	*- F
13	1		*O/S FOGLAMP (WCP)	Cracked	85.00 F	*85.00 F
14	1		*O/S FOGLAMP GARNISH (WCP)	Cracked	40.00 F	*40.00 F
15	1		*WASHER TANK (WCP)	Deformed	45.00 F	*45.00 F
Supplementary #1						
16	1		*O/S FOGLAMP BRACKET (WCP)	Cracked	55.00 F	*55.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,090.00	1,635.00
+ Margin on L,N Items 10.00/10.00% (S\$)	206.00	162.00
Total Parts (S\$)	2,296.00	1,797.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REINSTALL SENSOR, RESET SONAR CLEARANCE AND HID BULD WITH DIAGNOSTIC	New	280.00	40.00
3	LABOUR/PANEL BEATING (REPAIR SUPPORT PANEL, O/S FRT WHEELHOUSE)	New	700.00	550.00
4	SPRAY PAINTING 1)OS FRT DOOR, 2)OS FRT FENDER 3)FRT BUMPER 4)OS WHEELHOUSE PANEL 5)SUPPORT PANEL 6) BONNET	New	1,200.00	900.00
5	TO VACUUM, REOIL AND REGAS AIRCON	New	120.00	0.00
Gross Labour Cost (\$\$)			2,350.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >