ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint Singapore 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised

ESTIMATE

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
Attn: Accident Claims Department

L/Sup &?
Resurvey After Paint
4-6 days

Date :	05/02/2018
Vehicle No :	SJR2471Y
Veh Make/Model :	Honda Accord 2.0L
YOM :	2008
Chassis No :	MRHCP16308P020038
Date of Accident :	04/02/2018

No	Qty	Description	Amount $	
		List Items:-		
1	1	Rear bootlid	$ R 878.10	X
2	1	Rear bootlid badge	$ Na 32.10	—
3	1	Rear bootlid "Accord" emblem	$ Na 28.20	—
4	1	Rear bootlid "i-VTEC" emblem	$ Na 33.20	—
5	1	Rear bootlid inner lock	$ R 110.90	X
6	1	Rear bootlid weatherstrip	$ Sn 85.00	X
7	2	Rear bootlid stopper	$ Sn 18.00	X
8	1	Rear bootlid refelctor LH	$ Sn 172.20	X
9	1	Rear bootlid refelctor RH	$ Sn 172.20	X
10	1	LH taillamp	$ Sn 295.80	X
11	1	RH taillamp	$ Sn 295.80	X
12	1	Rear bumper	$ Rs 630.50	—
13	2	Rear bumper side retainer	$ N/S Dir 35.00	+
14	10	Rear bumper clip	$ Na 38.00	—
15	1	Rear bumper reinforcement	$ 145.60	?
16	1	End panel	$ 287.80	?
17	1	End panel top garnish	$ 97.70	?
18	6	End panel top garnish clip	$ 22.80	?
19	1	Rear floor panel board	$ Sn 133.00	X
20	1	Front bumper	$ R 976.00	?
21	2	Front bumper side retainer	$ Sn 46.00	X
22	10	Front bumper clip	$ 38.00	?
			Total - List Item	**$ 4,571.90**
			Less 20%	**$ 914.38**
			Total	**$ 3,657.52**

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint Singapore 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
Attn: Accident Claims Department

Date :	05/02/2018
Vehicle No :	SJR2471Y
Veh Make/Model :	Honda Accord 2.0L
YOM :	2008
Chassis No :	MRHCP16308P020038
Date of Accident :	04/02/2018

No	Qty	Description	Amount $	
		Balance c/f	**$ 3,657.52**	
		Special Nett Items:-		
1	1	Front number plate with holder	$ Nd 55.00	40/n
2	1	Rear number plate with holder	$ Sn 55.00	X
3	1 Set	Rear reverse sensor	$ 380.00	?
		Total - SN Item	**$ 490.00**	
		Labour Charges:-		
1		Spray painting on all affected area.	$ 1,200.00	800
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	$ 1,400.00	?
3		To apply anti rust treatment.	$ 120.00	?
4		To check wiring system & light.	$ 60.00	40
5		To check & adjust wheel aligment.	$ nn 120.00	X
6		To remove and replace reverse sensor.	$ 120.00	50
		Total - L/C	**$ 3,020.00**	
		Sub-Total	**$ 7,167.52**	
		7% GST	**$ 501.73**	
		Total	**$ 7,669.25**	